


# BUILDING CODE REVIEW

## WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

# CONTRACT No. 21-516

# TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK VILLAGE of SLEEPY HOLLOW, NEW YORK 10591



WESTCHESTER COUNTY

GENERAL PRESERVATION NOTES

March 19, 2021

2020 Existing Building Code of New York State (EBC) 2020 Building Code of New York State (BC), as referenced by EBC

## EBC Classification of work:

The reconstruction, replacement or renewal of any part of an existing building for the purpose of its maintenance or to correct damage.

#### <u>Historic Building (EBC Definition):</u>

- Any building or structure that is one or more of the following 1. Listed, or certified as eligible for listing, by the State Historic
- Preservation Officer or the Keeper of the National Register of Historic Places, in the National Register of Historic Places. 2. Designated as historic under an applicable state or local law.
- 3. Certified as a contributing resource within a National Register, state designated or locally designated historic district.
- Compliance: Building is listed on the National Register of Historic Places, and the NYS Historic Building Inventory.

#### **Chapter 3 Provisions for All Compliance Methods** 301.2 Administration, Repairs

Repairs shall comply with the requirements of Chapter 4. 305.1 Accessibility for Existing Buildings, Scope

Required: Accessibility provisions apply to maintenance, change of occupancy. additions and alterations to existing buildings, including those identified as

Provided: Provisions are not applicable to Repairs.

#### **Chapter 4 Repairs**

401.1 Scope Repairs to historic buildings need only comply with Chapter 12.

#### **Chapter 12 Historic Buildings**

## 1201.2 Report:

Identify each required safety feature that is in compliance with this chapter and where compliance with other chapters of these provisions would be damaging to the contributing historic features.

is occupied. Lock may always be opened with thumb turn from interior side.

Describe each feature that is not in compliance with these provisions and shall demonstrate how the intent of these provisions is complied with in providing an equivalent level of safety.

#### Provided: This code review constitutes the required report.

#### 1201.3 Special Occupancy Exception - Museums

Group B, Museums if less than 3,000 sq.ft. Area of building: 1,846 sq.ft. < 3,000 sq.ft.

Required: Means of maintaining doors in an open position to permit egress. Provided: Entrance door has no latch and is not locked when the building

# Required: Limit on building occupancy to an occupant load permitted by

the means of egress capacity.

Number of exits: Non-sprinklered, group B occ., one exit, the building is limited to 49 occupants (BC 1006.2.1). Stairs: Width 2'-9"; egress capacity 110 occupants (BC 1005.3.1) Exit door: Width 2'-8"; egress capacity 160 occupants (BC 1005.3.2)

#### 1201.4 Flood Hazard Areas

Permitted: Compliance with BC 1612 is not required for historic buildings Provided: Building is classified as historic because it is listed on the National Register of Historic Places, and the NYS Historic Building Inventory

1201.5 Unsafe Conditions Required: Conditions determined by the building official to be unsafe shall be remedied.

Provided: Guard rails with openings larger than 4 inches will be infilled with stainless steel netting. Access to the lantern level will not

## 1202.1 Repairs, General

Required: Hazardous materials, such as asbestos and lead-based paint, shall not be used. Provided: Hazardous materials are prohibited by the specifications.

#### 1202.2 Repairs, Replacement

Permitted/required: Replacement of existing or missing features using original materia Replacement glazing in hazardous locations shall comply with the safety glazing requirements of Chapter 24 of BC.

Provided: Original materials are specified for repairs and replacement. Laminated safe glass is specified for all glass replacement.

Provided: The building will not undergo alteration, change of occupancy, or be moved

#### 1203.1 Fire Safety, Scope

Required: Historic buildings undergoing alterations, changes of occupancy, or that are moved shall comply with Section 1203.

Therefore compliance with Section 1203 is not required.

#### 1204 Change of Occupancy

Not applicable; not a change of occupancy

## 1205 Structural

Required: Historic buildings shall comply with the applicable structural provisions for the work as classified in Chapter 4 or 5. Exception 1: The building official shall be authorized to accept existing floors and existing live loads.

Exception 2: Repair of substantial structural damage is not required to comply with Sections 405.2.3 and 405.2.4. Substantial structural damage shall be repaired in accordance with Section 405.2.1.

Provided: There is no substantial structural damage. Repairs are for the purpose of preventing future damage. Structural repair provisions of Chapter 4 are not applicable.

#### 1206 Relocated Buildings Not applicable.

#### 2020 Energy Conservation Construction Code

Chapter 5 [CE] Existing Buildings Per paragraph C501.6, provisions of the Energy Code are not mandatory for Historic Buildings.

## SHEET

# NO. SHEET TITLE

## TITLE SHEET SITE PLAN and GENERAL NOTES BASEMENT AND FIRST FLOOR PLANS

ELECTRICAL REMOVAL PLANS

SECOND AND THIRD FLOOR PLANS FOURTH, FIFTH, AND SIXTH FLOOR PLANS EXTERIOR ELEVATION AND SECTION DETAILS WINDOW DETAILS **DETAILS** CAISSON REPAIR ELEVATION AND SECTION S-201 STRUCTURAL PLANS UNFOLDED CAISSON ELEVATION AND DETAILS ELECTRICAL SITE PLAN, RISER DETAIL, NOTES

ELECTRICAL AND LIGHTING PLANS ELECTRICAL ELEVATIONS CATHODIC PROTECTION - GENERAL NOTES CATHODIC PROTECTION - ICCP LAYOUT CATHODIC PROTECTION - SYSTEM COMPONENT DTLS CATHODIC PROTECTION - POWER SUPPLY DETAILS CATHODIC PROTECTION - WIRING DIAGRAM

CATHODIC PROTECTION - ANODE LAYOUT

**CATHODIC PROTECTION - ZONE CONNECTIONS** 

DPW FILE NO

8-12-T-29 8-12-A-30 8-12-A-31 8-12-A-32 8-12-A-33 8-12-A-34 8-12-A-35 8-12-A-36

8-12-A-37 8-12-S-38 8-12-S-39 8-12-S-40 8-12-E-41 8-12-E-42 8-12-E-43 8-12-E-44

8-12-E-51

8-12-E-45 8-12-E-46 8-12-E-47 8-12-E-48 8-12-E-49 8-12-E-50

#### STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522

Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

REVISION NUMBER	DATE	MADE BY	APP'D BY	REVISION
DECORD DRAWING CERTIFICATION				

AVAILABLE ONLINE AT http://www.nps.gov/hps/tps/standquide/.

RE-INSTALLATION IN THE ORIGINAL CONFIGURATION.

ALL EXISTING MATERIALS AND COMPONENTS OF THE LIGHTHOUSE ARE TO BE

HISTORIC ITEMS SHALL NOT BE DAMAGED, REMOVED OR ALTERED EXCEPT

RESTORATION. IF TEMPORARY REMOVAL IS REQUIRED, WORK SHALL BE

AS INDICATED OR AS OTHERWISE REQUIRED FOR PRESERVATION OR

BE DOCUMENTED PHOTOGRAPHICALLY PRIOR TO REMOVAL, AND ALL

CONSIDERED HISTORIC UNLESS SPECIFICALLY INDICATED AS "NON-HISTORIC".

DONE UNDER THE ARCHITECT'S SUPERVISION, THE EXISTING CONDITION SHALL

FASTENERS AND COMPONENTS SHALL BE PROTECTED AND RESTORED FOR

RECORD	DRAWING	CERTIFICATION

AS BUILT - CHANGES AS NOTED AS BUILT - NO CHANGES

CONTRACTOR PROJECT COORDINATOR NAME SIGNATURE DATE

CONTRACT DPW DRAWING WESTCHESTER COUNTY, NEW YORK NUMBER: DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION 21 - 516SHEET NO. 01 OF 23 DIVISION OF ENGINEERING

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY

SHALL AFFIX TO THE DOCUMENT THEIR SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY THEIR SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION. IN CHARGE OF STEPHEN TILLY, R.A. CHECKED BY STEPHEN TILLY, R.A.

MADE BY STEPHEN TILLY, R.A.

IT IS A VIOLATION OF NYS LAW FOR ANY PERSON TO

ALTER THIS DOCUMENT IN ANY WAY, UNLESS ACTING

UNDER THE DIRECTION OF A LICENSED PROFESSIONAL

ENGINEER. IF A DOCUMENT BEARING THE SEAL OF AN ENGINEER IS ALTERED, THE ALTERING ENGINEER

> ADAM KAPLINSKI, R.A. ASSOCIATE ARCHITECT DEPARTMENT OF PUBLIC WORKS & TRANSPORTATION

APPROVED FOR CONSTRUCTION GAYLE KATZMAN, P.E.

FIRST DEPUTY COMMISSIONER DEPARTMENT OF PUBLIC WORKS & TRANSPORTATION

KATHLEEN O'CONNOR COMMISSIONER DEPARTMENT OF PARKS, RECREATION & CONSERVATION

APPROVED FOR CONSTRUCTION

HUGH J. GREECHAN JR., P.E. COMMISSIONER DEPARTMENT OF PUBLIC WORKS

APPROVED FOR CONSTRUCTION


RECOMMENDED FOR DESIGN

& TRANSPORTATION

TITLE SHEET

SCALE: n/a DATE: 08-20-2021 DPW FILE NO. 8-12-T-29

A - 000



- I. PROTECT ALL EXISTING SITE IMPROVEMENTS INCLUDING BUT NOT LIMITED TO, SITE WALLS, PAVING, TREES, AND LANDSCAPE PLANTING, AND RESTORE ANY DAMAGED ITEMS TO CONDITION EXISTING AT THE START OF WORK.
- 2. COMPLY WITH ALL FEDERAL, STATE, AND LOCAL ENVIRONMENTAL REGULATIONS AND PROVIDE PROTECTION AGAINST DEBRIS, SILT OR CONTAMINATION ENTERING THE HUDSON RIVER.
- 3. SILT FENCE SHALL BE INSTALLED AS REQUIRED PRIOR TO ANY EXCAVATION OR SITE DISTURBANCE. PROVIDE SOIL EROSION AND SEDIMENT CONTROL PRACTICES IN ACCORDANCE WITH NEW YORK-GUIDELINES FOR URBAN EROSION & SEDIMENT CONTROL, LATEST EDITION.
- 4. INSTALL ALL SITE PROTECTION PRIOR TO COMMENCEMENT OF DEMOLITION AND CONSTRUCTION OPERATIONS. MAINTAIN SITE PROTECTION FOR ENTIRE DURATION OF CONSTRUCTION. 'CONSTRUCTION FENCE' SHALL BE 4'-0" HIGH WOOD SLAT SNOW FENCE.
- 5. UPON COMPLETION OF CONSTRUCTION AND PRIOR TO FINAL ACCEPTANCE, REMOVE ALL TEMPORARY PROTECTION AND OTHER TEMPORARY ITEMS AND RESTORE SITE TO ITS ORIGINAL CONDITION.
- 6. CONSTRUCTION VEHICLE ACCESS IS TO BE THROUGH EXISTING PAVED PARKING LOTS. ALL VEHICULAR TRAFFIC IS RESTRICTED TO PAVED AREAS. CONTRACTOR SHALL INSURE THAT ALL VEHICLES LEAVING THE CONSTRUCTION SITE ARE THOROUGHLY CLEANED OF ANY MUD OR DEBRIS PRIOR TO ENTERING ROADWAY.
- BEFORE EXCAVATION OR DIGGING OF ANY KIND IS UNDERTAKEN, CONTRACTOR SHALL CONTACT ALL LOCAL UTILITIES AND AUTHORITIES AND UTILIZE THE NATIONAL "CALL BEFORE YOU DIG" HOTLINE AVAILABLE TO LOCATE AND IDENTIFY ANY AND ALL POSSIBLE UNDERGROUND UTILITIES. CONTRACTOR SHALL BE RESPONSIBLE TO PROTECT AND PRESERVE ANY EXISTING CONDITIONS AND COORDINATE WITH NEW WORK.

#### ENVIRONMENTAL AND SAFETY NOTES

- I. REPORTS OF ASSESSMENTS TO IDENTIFY THE PRESENCE OF ASBESTOS CONTAINING MATERIALS (ACM) AND LEAD-BASED PAINT (LBP) ARE INCLUDED IN THE SPECIFICATIONS. THESE REPORTS ARE FURNISHED FOR THE USE AND CONVENIENCE OF THE CONTRACTOR, AND NEITHER THE ARCHITECT NOR THE OWNER GUARANTEE THEIR COMPLETENESS AND ACCURACY. THE CONTRACTOR IS SOLELY RESPONSIBLE FOR THE PERFORMANCE OF HIS WORK IN ACCORDANCE WITH ALL FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS.
- 2. WHEREVER REMOVAL OF HAZARDOUS MATERIALS IS REQUIRED FOR THIS WORK, IT SHALL BE PERFORMED IN COMPLIANCE WITH ALL FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS REGARDING ENVIRONMENTAL PROTECTION, HEALTH, AND SAFETY.
- 3. THE CONTRACTOR SHALL ESTABLISH MEANS AND METHODS TO PROTECT THE HUDSON RIVER FROM CONTAMINATION BY PAINT PARTICLES AND RESIDUE DUE TO PAINT REMOVAL OPERATIONS, REGARDLESS OF WHETHER OR NOT LEAD IS INVOLVED. THESE MEANS AND METHODS SHALL BE REVIEWED WITH THE OWNER AND ARCHITECT PRIOR TO COMMENCEMENT OF WORK.

#### GENERAL PRESERVATION NOTES

- THE TARRYTOWN LIGHTHOUSE IS A HISTORIC STRUCTURE, LISTED ON THE NATIONAL REGISTER OF HISTORIC PLACES. THE INTENT OF THE WORK DESCRIBED IN THESE DRAWINGS IS TO RESTORE AND PRESERVE THE STRUCTURE IN A MANNER CONSISTENT WITH "THE SECRETARY OF THE INTERIOR'S STANDARDS FOR THE TREATMENT OF HISTORIC PROPERTIES". ALL BIDDERS SHALL BE FAMILIAR WITH THE INTENT OF THIS DOCUMENT, WHICH IS AVAILABLE ONLINE AT:
- https://www.nps.gov/tps/standards/rehabilitation/rehab/index.htm
- 2. ALL EXISTING MATERIALS AND COMPONENTS OF THE LIGHTHOUSE ARE TO BE CONSIDERED HISTORIC UNLESS SPECIFICALLY INDICATED AS "NON-HISTORIC". HISTORIC ITEMS SHALL NOT BE DAMAGED, REMOVED OR ALTERED EXCEPT AS INDICATED OR AS OTHERWISE REQUIRED FOR PRESERVATION OR RESTORATION. IF TEMPORARY REMOVAL IS REQUIRED, WORK SHALL BE DONE UNDER THE ARCHITECT'S SUPERVISION, THE EXISTING CONDITION SHALL BE DOCUMENTED PHOTOGRAPHICALLY PRIOR TO REMOVAL, AND ALL FASTENERS AND COMPONENTS SHALL BE PROTECTED AND RESTORED FOR RE-INSTALLATION IN THE ORIGINAL CONFIGURATION.
- SECURE LOCATION AS DIRECTED BY OWNER.

#### COFFER DAM NOTES

- I. ALL COFFER DAM WORK IS TO BE COORDINATED WITH SPECIFICATION SECTION #01-5010. FABRICATION AND INSTALLATION OF COFFER DAM NOT TO PROCEED UNTIL ALL SUBMITTALS HAVE BEEN APPROVED AND RETURNED.
- 2. CONTRACTOR RESPONSIBLE FOR ANY ADDITIONAL PERMITS OR APPROVALS BASED UPON THEIR PROPOSED COFFER DAM STRATEGY, MATERIALS, AND/OR INSTALLATION METHODS.
- 3. CONTRACTOR RESPONSIBLE FOR ALL DEWATERING OF COFFER DAM AFTER CONSTRUCTION OF DAM. CONTRACTOR TO COORDINATE SETTLING TANKS FOR ALL WATER THAT IS TO BE RETURNED TO THE HUDSON RIVER THROUGHOUT THE LIFE OF THE COFFER DAM SCOPE OF WORK, AS REQUIRED.
- 4. CONTRACTOR TO MAINTAIN COFFER DAM AND ALL PROTECTIONS THROUGHOUT THE LIFE OF THE SCOPE OF WORK THAT REQUIRES THE COFFER

STEPHEN TILLY, Architect

22 Elm Street, Dobbs Ferry, New York 10522 Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970

MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC

4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

CONTRACT DPW DRAWING NUMBER: NUMBER:

DRAWING TITLE:

SITE PLAN AND

**GENERAL NOTES** 

DRAWING NUMBER:

21-516 | 8-12-A-30 SHEET NO .: SHEET NO .:

DPW FILE NO. 8-12-A-30

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY SITE PLAN AND GENERAL NOTES


REVISION


NUMBER


BY

BY

scale: as noted DATE: 08-20-2021







REVISION DATE

MADE APP'D

BY

BY



REVISION

#### SCOPE OF WORK

- A <u>TOWER EXTERIOR:</u> Including exterior surfaces and components from top of caisson to top of lantern vent ball, cast iron window trim, cantilevered galleries, brackets, railings, flue, bell housing, 1st story protective canopy and supporting columns. Excluding windows, doors, lantern glazing, fog bell, caisson (see Caisson Repairs, below), concrete paving. Install protection as necessary to comply with NYSDEC permit requirement to prevent contamination of the Hudson River.
- I. Remove paint and rust scale from all exterior cast iron surfaces using specified techniques. Remove non-historic items as indicated on drawings. See Appendix 3 - Lead Paint Testing Inspection Report for further information.
- 2. Remove corrosion within joints and decorative trim. Immediately apply specified primer paint to newly exposed and cleaned metal surfaces.
- 3. Inspect metal surfaces and components to identify areas of severe erosion, deformation, mechanical breakdown, delamination, failure, or loose components or fasteners and repair as specified. Follow architect's instructions for
- 4. Inspect construction joints for proper sealant performance. Remove and replace deteriorated, missing, or non-performing sealant. Inspect enclosure and guttering system for holes and leaks into the interior, and repair as directed by architect. See drawings for locations of known leaks.
- 5. Apply NEPCOAT qualified high performance primer and finish coating as specified. Provide non-slip agaregate material at painted metal deck surfaces. Refer to color schedule.
- B. <u>MINDOWS:</u> Including 8 openings at the 1st, 2nd, and 3rd floors and 8 porthole openings at the 4th floor. Except lantern
- I. WINDOWS W-I THROUGH W-8 (double hung): Remove non-historic security gratings, glazing and sashes. Historic wood window frames and interior casings shall remain. Remove excessive paint buildup on historic wood components and restore damaged and rotted wood as specified. Install new custom made double-hung wood windows and weatherstripping within existing frames. Field paint all windows and trim.
- 2. WINDOWS W-9 THROUGH W-16 (portholes): Carefully remove interior trim at 8 porthole windows. Restore damaged or rotted wood as specified and install fixed laminated glass. Reinstall interior trim and paint all exposed wood.
- C. <u>EXTERIOR ELECTRICAL WORK</u>: Provide new electrical service and exterior lighting fixtures as indicated on electrical
- D. <u>INTERIOR ELECTRICAL WORK:</u> Provide new electrical panel. Replace interior lighting fixtures, convenience outlets, and
- wiring as indicated. Remove abandoned wiring. E. <u>EXTERIOR DECK AT FIRST FLOOR:</u> Remove top layer of concrete, install cathodic protection components, and install new
- concrete topping slab to original elevations. F. <u>WOOD FLOORING:</u> Remove all metal floor plates, plugs, and sleeves in wood flooring. Repair damaged wood and where indicated on plans, using filler compound or Dutchmen as appropriate. Install patches or plugs at floor penetrations as

detailed (Note: patches at historic floor openings shall be made with materials similar to surrounding wood flooring, but are


G. INTERIOR WOOD DOORS, PARTITIONS, AND PANELING: Construct and/or restore interior wood elements where shown to match existing historic elements. Fabricate and install reproduction doors and hardware in openings where indicated.

not intended to be invisible). Sand floor to remove previous finishes and finish with clear polyurethane.

- Remove excessive paint buildup using specified methods. Paint all new and existing wood (refer to paint color schedule). H. <u>EXTERIOR DOORS</u>: Remove exterior doors at First and Fifth Floors. Fabricate and install new doors and hardware as indicated on drawings and specifications.
- . <u>BASEMENT</u>: Except caisson repairs and first floor structural plate repairs.

additional repairs in cases of structural failure or weakening.

- I. Remove debris, dirt and sediment from basement, clean and expose concrete floor.
- 2. Remove and dispose of furnace, leaving main flue in place. Seal breached flue opening with metal plate, gasket and
- 3. STAIR TO BASEMENT: Remove existing wood stair to basement. Fabricate, install and paint new pressure treated wood stair and cast-in-place concrete bottom landing as detailed. See drawing 2/A-301 for further information.
- 4. Remove loose paint and rust from basement side of stair partition, underside of metal stair above and other metal surfaces, prime and paint (except 1st floor plates).
- 5. Re-point brick masonry where directed by architect. For bidding purposes assume 200 sq.ft. of wall area.
- J. NOT USED K. LANTERN REPAIRS (6th floor).
- I. LANTERN GLAZING: Remove 10 non-historic glazing panels. Remove astragals, glazing stops and fasteners--clean and protect for re-installation. Remove excessively built-up paint and clean metal mullions, head and sill. Fabricate any missing metal components to match historic materials and profiles. Install specified glazing, glazing compound, and removed historic and reproduced stops and astragals using historic and matching fasteners. Paint all exposed metal components (coordinate with exterior painting).
- LANTERN INTERIOR: Repair damaged wood interior walls and trim as indicated on drawings. Sand lightly to remove heavily built-up paint on wood surfaces. Remove loose paint on interior metal surfaces. Repaint interior wood and metal surfaces (see paint color schedule).
- 3. FRESNEL LENS AND LIGHT: Remove solar array and associated equipment serving existing reproduction Light and provide electrical service to Light as indicated on electrical drawings. Clean and refurbish Light assembly as
- L. <u>CATHODIC PROTECTION SYSTEM</u>: Install cathodic protection system as described on drawings and specifications, and coordinate with electrical work.
- M. <u>CAISSON REPAIRS</u>: Construct a temporary coffer dam and create a dry work space around entire caisson. Reposition rip-rap boulders as necessary for access to caisson. Perform caisson repair work indicated on structural drawings. Remove paint and rust from metal surfaces and apply Thermal Sprayed Coating (Metallization) and high performance paint coating. Restore rip-rap to approximate original locations after completion of work.
- N. <u>FIRST FLOOR STRUCTURE AND FLOOR FINISH.</u>
- I. Carefully remove 1st floor historic wood flooring boards, documenting location of each board and store for later reinstallation.
- 2. Perform repairs to 1st floor iron structural floor plates as indicated on structural drawings.
- 3. Reinstall removed historic floor boards using original installation techniques. Repair damaged wood, using filler compound, Dutchmen, or matching new floor boards as appropriate. Install patches or plugs at floor penetrations as detailed. Sand and refinish as indicated for wood flooring on other floors. Architect to inspect flooring upon removal and determine preservation treatment, if any.
- O. <u>GUARDRAIL INFILL PANEL</u>: Remove chicken wire infill at guardrails on 1st and 5th floor galleries. Install specified stainless steel cable netting on all guardrails at 1st and 5th floor galleries as detailed.
- P. BRIDGE AND ISLAND.
- I. Perform repairs to perimeter beam/retaining wall of Island as indicated on drawing A-010 for further information.
- 2. On Island, remove asphalt paving and damaged or unstable areas of concrete paving base. Repair concrete base as required and install specified asphalt paver block finish.
- 3. Fabricate and install security gate at land end of bridge.
- Q. NOT USED
- R. NOT USED
- S. <u>FLUE REPAIRS</u>: Modify flue cap to prevent rainwater entry. Fabricate and install closure with cleanout for corroded flue
- T. <u>MISCELLANEOUS MINOR REPAIRS</u>: Provide threaded caps on open ends of abandoned waste pipes per plumbing code.



STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522 Structural Engineer: Structures North Consulting Engineers, Inc.

60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

CONTRACT | DPW DRAWING NUMBER: NUMBER:

WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

21-516 **8-12-A-31** SHEET NO.: 03 of 23 scale: as noted DATE: 08-20-2021 DPW FILE NO.

8-12-A-31


DRAWING TITLE:


BASEMENT & FIRST

FLOOR PLAN


DRAWING NUMBER:

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY BASEMENT AND FIRST FLOOR PLAN









3 2nd FLOOR NEW WORK




# REVISION NUMBER DATE BY BY REVISION

#### SCOPE OF WORK

- A <u>TOWER EXTERIOR</u>: Including exterior surfaces and components from top of caisson to top of lantern vent ball, cast iron window trim, cantilevered galleries, brackets, railings, flue, bell housing, 1st story protective canopy and supporting columns. Excluding windows, doors, lantern glazing, fog bell, caisson (see Caisson Repairs, below), concrete paving. Install protection as necessary to comply with NYSDEC permit requirement to prevent contamination of the Hudson River.
- Remove paint and rust scale from all exterior cast iron surfaces using specified techniques. Remove non-historic items as indicated on drawings. See Appendix 3 - Lead Paint Testing Inspection Report for further information.
- 2. Remove corrosion within joints and decorative trim. Immediately apply specified primer paint to newly exposed and cleaned metal surfaces.
- 3. Inspect metal surfaces and components to identify areas of severe erosion, deformation, mechanical breakdown, delamination, failure, or loose components or fasteners and repair as specified. Follow architect's instructions for
- 4. Inspect construction joints for proper sealant performance. Remove and replace deteriorated, missing, or non-performing sealant. Inspect enclosure and guttering system for holes and leaks into the interior, and repair as directed by architect. See drawings for locations of known leaks.
- 5. Apply NEPCOAT qualified high performance primer and finish coating as specified. Provide non-slip aggregate material at painted metal deck surfaces. Refer to color schedule.
- B. <u>WINDOWS:</u> Including 8 openings at the 1st, 2nd, and 3rd floors and 8 porthole openings at the 4th floor. Except lantern
- I. WINDOWS W-I THROUGH W-8 (double hung): Remove non-historic security gratings, glazing and sashes. Historic wood window frames and interior casings shall remain. Remove excessive paint buildup on historic wood components and restore damaged and rotted wood as specified. Install new custom made double-hung wood windows and weatherstripping within existing frames. Field paint all windows and trim.
- 2. WINDOWS W-9 THROUGH W-16 (portholes): Carefully remove interior trim at 8 porthole windows. Restore damaged or rotted wood as specified and install fixed laminated glass. Reinstall interior trim and paint all exposed wood.
- C. <u>EXTERIOR ELECTRICAL WORK</u>: Provide new electrical service and exterior lighting fixtures as indicated on electrical drawings.
- D. <u>INTERIOR ELECTRICAL WORK</u>: Provide new electrical panel. Replace interior lighting fixtures, convenience outlets, and wiring as indicated. Remove abandoned wiring.
- E. <u>EXTERIOR DECK AT FIRST FLOOR:</u> Remove top layer of concrete, install cathodic protection components, and install new concrete topping slab to original elevations.
- F. <u>WOOD FLOORING</u>: Remove all metal floor plates, plugs, and sleeves in wood flooring. Repair damaged wood and where indicated on plans, using filler compound or Dutchmen as appropriate. Install patches or plugs at floor penetrations as detailed (Note: patches at historic floor openings shall be made with materials similar to surrounding wood flooring, but are not intended to be invisible). Sand floor to remove previous finishes and finish with clear polyurethane.
- G. <u>INTERIOR WOOD DOORS, PARTITIONS, AND PANELING:</u> Construct and/or restore interior wood elements where shown to match existing historic elements. Fabricate and install reproduction doors and hardware in openings where indicated. Remove excessive paint buildup using specified methods. Paint all new and existing wood (refer to paint color schedule).
- H. <u>EXTERIOR DOORS</u>: Remove exterior doors at First and Fifth Floors. Fabricate and install new doors and hardware as indicated on drawings and specifications.
- BASEMENT: Except caisson repairs and first floor structural plate repairs.

additional repairs in cases of structural failure or weakening.

- I. Remove debris, dirt and sediment from basement, clean and expose concrete floor.
- 2. Remove and dispose of furnace, leaving main flue in place. Seal breached flue opening with metal plate, gasket and screws.
- 3. STAIR TO BASEMENT: Remove existing wood stair to basement. Fabricate, install and paint new pressure treated wood stair and cast-in-place concrete bottom landing as detailed. See drawing 2/A-301 for further information.
- 4. Remove loose paint and rust from basement side of stair partition, underside of metal stair above and other metal surfaces, prime and paint (except 1st floor plates).
- Re-point brick masonry where directed by architect. For bidding purposes assume 200 sq.ft. of wall area.
   NOT USED
- K. LANTERN REPAIRS (6th floor).
- I. LANTERN GLAZING: Remove IO non-historic glazing panels. Remove astragals, glazing stops and fasteners--clean and protect for re-installation. Remove excessively built-up paint and clean metal mullions, head and sill. Fabricate any missing metal components to match historic materials and profiles. Install specified glazing, glazing compound, and removed historic and reproduced stops and astragals using historic and matching fasteners. Paint all exposed metal components (coordinate with exterior painting).
- 2. LANTERN INTERIOR: Repair damaged wood interior walls and trim as indicated on drawings. Sand lightly to remove heavily built-up paint on wood surfaces. Remove loose paint on interior metal surfaces. Repaint interior wood and metal surfaces (see paint color schedule).
- 3. FRESNEL LENS AND LIGHT: Remove solar array and associated equipment serving existing reproduction Light and provide electrical service to Light as indicated on electrical drawings. Clean and refurbish Light assembly as directed by manufacturer.
- <u>CATHODIC PROTECTION SYSTEM:</u> Install cathodic protection system as described on drawings and specifications, and coordinate with electrical work.
- M. <u>CAISSON REPAIRS</u>: Construct a temporary coffer dam and create a dry work space around entire caisson. Reposition rip-rap boulders as necessary for access to caisson. Perform caisson repair work indicated on structural drawings. Remove paint and rust from metal surfaces and apply Thermal Sprayed Coating (Metallization) and high performance paint coating. Restore rip-rap to approximate original locations after completion of work.
- N. FIRST FLOOR STRUCTURE AND FLOOR FINISH.
- I. Carefully remove 1st floor historic wood flooring boards, documenting location of each board and store for later reinstallation.
- 2. Perform repairs to 1st floor iron structural floor plates as indicated on structural drawings.
- 3. Reinstall removed historic floor boards using original installation techniques. Repair damaged wood, using filler compound, Dutchmen, or matching new floor boards as appropriate. Install patches or plugs at floor penetrations as detailed. Sand and refinish as indicated for wood flooring on other floors. Architect to inspect flooring upon removal and determine preservation treatment, if any.
- O. <u>GUARDRAIL INFILL PANEL</u>: Remove chicken wire infill at guardrails on 1st and 5th floor galleries. Install specified stainless steel cable netting on all guardrails at 1st and 5th floor galleries as detailed.
- P. <u>BRIDGE AND ISLAND.</u>
- Perform repairs to perimeter beam/retaining wall of Island as indicated on drawing A-OIO for further information.
   On Island, remove asphalt paving and damaged or unstable areas of concrete paving base. Repair concrete base as required and install specified asphalt paver block finish.
- Fabricate and install security gate at land end of bridge.
- Q. NOT USED
- R. NOT US
- S. <u>FLUE REPAIRS</u>: Modify flue cap to prevent rainwater entry. Fabricate and install closure with cleanout for corroded flue offset at 3rd floor.
- T. MISCELLANEOUS MINOR REPAIRS: Provide threaded caps on open ends of abandoned waste pipes per plumbing code.



STEPHEN TILLY, Architect
22 Elm Street, Dobbs Ferry, New York 10522
Structural Engineer: Structures North Consulting Engineers, Inc.
60 Washington St., Suite 401, Salem, MA 01970

60 Washington St., Suite 401, Salem, MA 01970

MEP Engineer: Tietjen Venegas Conulting Engineers
68 Purchase Street, Rye, New York 10580

Cathodic Protection Consultant: Echem Consultants, LLC

SECOND & THIRD FLOOR PLANS

DRAWING NUMBER:

CONTRACT | DPW DRAWING

DRAWING TITLE:


4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601
WESTCHESTER COUNTY, NEW YORK
DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION

NUMBER: NUMBER: 21-516 8-12-A-32 SHEET NO.: 04 of 23

TARRYTOWN LIGHTHOUSE RESTORATION
KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY
SECOND AND THIRD FLOOR PLANS


DIVISION OF ENGINEERING

SCALE: as noted
DATE: 08-20-2021
DPW FILE NO.
8-12-A-32



#### SCOPE OF WORK

- A <u>TOWER EXTERIOR:</u> Including exterior surfaces and components from top of caisson to top of lantern vent ball, cast iron window trim, cantilevered galleries, brackets, railings, flue, bell housing, 1st story protective canopy and supporting columns. Excluding windows, doors, lantern glazing, fog bell, caisson (see Caisson Repairs, below), concrete paving. Install protection as necessary to comply with NYSDEC permit requirement to prevent contamination of the Hudson River.
- I. Remove paint and rust scale from all exterior cast iron surfaces using specified techniques. Remove non-historic items as indicated on drawings. See Appendix 3 - Lead Paint Testing Inspection Report for further information.
- 2. Remove corrosion within joints and decorative trim. Immediately apply specified primer paint to newly exposed and cleaned metal surfaces.
- 3. Inspect metal surfaces and components to identify areas of severe erosion, deformation, mechanical breakdown, delamination, failure, or loose components or fasteners and repair as specified. Follow architect's instructions for
- 4. Inspect construction joints for proper sealant performance. Remove and replace deteriorated, missing, or non-performing sealant. Inspect enclosure and guttering system for holes and leaks into the interior, and repair as directed by architect. See drawings for locations of known leaks.
- 5. Apply NEPCOAT qualified high performance primer and finish coating as specified. Provide non-slip aggregate material at painted metal deck surfaces. Refer to color schedule.
- B. <u>WINDOWS:</u> Including 8 openings at the 1st, 2nd, and 3rd floors and 8 porthole openings at the 4th floor. Except lantern
- I. WINDOWS W-I THROUGH W-8 (double hung): Remove non-historic security gratings, glazing and sashes. Historic wood window frames and interior casings shall remain. Remove excessive paint buildup on historic wood components and restore damaged and rotted wood as specified. Install new custom made double-hung wood windows and weatherstripping within existing frames. Field paint all windows and trim.
- 2. WINDOWS W-9 THROUGH W-16 (portholes): Carefully remove interior trim at 8 porthole windows. Restore damaged or rotted wood as specified and install fixed laminated glass. Reinstall interior trim and paint all exposed wood.
- C. <u>EXTERIOR ELECTRICAL WORK</u>: Provide new electrical service and exterior lighting fixtures as indicated on electrical
- D. <u>INTERIOR ELECTRICAL WORK:</u> Provide new electrical panel. Replace interior lighting fixtures, convenience outlets, and
- wiring as indicated. Remove abandoned wiring. E. <u>EXTERIOR DECK AT FIRST FLOOR:</u> Remove top layer of concrete, install cathodic protection components, and install new
- F. <u>WOOD FLOORING:</u> Remove all metal floor plates, plugs, and sleeves in wood flooring. Repair damaged wood and where indicated on plans, using filler compound or Dutchmen as appropriate. Install patches or plugs at floor penetrations as detailed (Note: patches at historic floor openings shall be made with materials similar to surrounding wood flooring, but are not intended to be invisible). Sand floor to remove previous finishes and finish with clear polyurethane.
- 6. INTERIOR WOOD DOORS, PARTITIONS, AND PANELING: Construct and/or restore interior wood elements where shown to match existing historic elements. Fabricate and install reproduction doors and hardware in openings where indicated. Remove excessive paint buildup using specified methods. Paint all new and existing wood (refer to paint color schedule).
- H. <u>EXTERIOR DOORS</u>: Remove exterior doors at First and Fifth Floors. Fabricate and install new doors and hardware as indicated on drawings and specifications.
- . <u>BASEMENT</u>: Except caisson repairs and first floor structural plate repairs.
- I. Remove debris, dirt and sediment from basement, clean and expose concrete floor.
- 2. Remove and dispose of furnace, leaving main flue in place. Seal breached flue opening with metal plate, gasket and screws.
- 3. STAIR TO BASEMENT: Remove existing wood stair to basement. Fabricate, install and paint new pressure treated wood stair and cast-in-place concrete bottom landing as detailed. See drawing 2/A-301 for further information.
- 4. Remove loose paint and rust from basement side of stair partition, underside of metal stair above and other metal surfaces, prime and paint (except 1st floor plates).
- 5. Re-point brick masonry where directed by architect. For bidding purposes assume 200 sq.ft. of wall area.
- K. LANTERN REPAIRS (6th floor).
- I. LANTERN GLAZING: Remove 10 non-historic glazing panels. Remove astragals, glazing stops and fasteners--clean and protect for re-installation. Remove excessively built-up paint and clean metal mullions, head and sill. Fabricate any missing metal components to match historic materials and profiles. Install specified glazing, glazing compound, and removed historic and reproduced stops and astragals using historic and matching fasteners. Paint all exposed metal components (coordinate with exterior painting).
- LANTERN INTERIOR: Repair damaged wood interior walls and trim as indicated on drawings. Sand lightly to remove heavily built-up paint on wood surfaces. Remove loose paint on interior metal surfaces. Repaint interior wood and metal surfaces (see paint color schedule).
- 3. FRESNEL LENS AND LIGHT: Remove solar array and associated equipment serving existing reproduction Light and provide electrical service to Light as indicated on electrical drawings. Clean and refurbish Light assembly as
- L. <u>CATHODIC PROTECTION SYSTEM</u>: Install cathodic protection system as described on drawings and specifications, and coordinate with electrical work.
- M. <u>CAISSON REPAIRS</u>: Construct a temporary coffer dam and create a dry work space around entire caisson. Reposition rip-rap boulders as necessary for access to caisson. Perform caisson repair work indicated on structural drawings. Remove paint and rust from metal surfaces and apply Thermal Sprayed Coating (Metallization) and high performance paint coating. Restore rip-rap to approximate original locations after completion of work.
- N. <u>FIRST FLOOR STRUCTURE AND FLOOR FINISH.</u>
- I. Carefully remove 1st floor historic wood flooring boards, documenting location of each board and store for later reinstallation.
- 2. Perform repairs to 1st floor iron structural floor plates as indicated on structural drawings.
- 3. Reinstall removed historic floor boards using original installation techniques. Repair damaged wood, using filler compound, Dutchmen, or matching new floor boards as appropriate. Install patches or plugs at floor penetrations as detailed. Sand and refinish as indicated for wood flooring on other floors. Architect to inspect flooring upon removal and determine preservation treatment, if any.
- O. <u>GUARDRAIL INFILL PANEL</u>: Remove chicken wire infill at guardrails on 1st and 5th floor galleries. Install specified stainless steel cable netting on all guardrails at 1st and 5th floor galleries as detailed.
- P. BRIDGE AND ISLAND.
- I. Perform repairs to perimeter beam/retaining wall of Island as indicated on drawing A-010 for further information.
- 2. On Island, remove asphalt paving and damaged or unstable areas of concrete paving base. Repair concrete base as required and install specified asphalt paver block finish.
- 3. Fabricate and install security gate at land end of bridge.
- R. NOT USED
- S. <u>FLUE REPAIRS</u>: Modify flue cap to prevent rainwater entry. Fabricate and install closure with cleanout for corroded flue
- T. <u>MISCELLANEOUS MINOR REPAIRS</u>: Provide threaded caps on open ends of abandoned waste pipes per plumbing code. DRAWING TITLE:



STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522 Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970

MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

FOURTH, FIFTH & SIXTH FLOOR PLANS

DRAWING NUMBER

CONTRACT DPW DRAWING NUMBER: NUMBER: WESTCHESTER COUNTY, NEW YORK 21-516 | 8-12-A-33 DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION


SHEET NO.: 05 of 23


scale: as noted DATE: 08-20-2021 DPW FILE NO.


TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY FOURTH, FIFTH, & SIXTH FLOOR PLANS


DIVISION OF ENGINEERING

8-12-A-33










2" X I/4" BENT PLATE FOR PADLOCK HASP
3/4" X 3/4" STEEL BAR PICKETS  2" X 2" GATE FRAME  4" X 4" STEEL TUBE JAMB POST
7" X 7" BASE PLATE W 304 STAINLESS STEEL 5/8" X 7" EXPANSION BOLTS AND CAULKED
GATE - JAMB AND HASP DETAILS  SCALE: 1 1/2" = 1'-0"

	DOOR SCHEDULE								
TAG	DESCRIPTION	SCOPE OF WORK	DIMENSIONS	FRAME	FINISH	DETAILS	REMARKS		
101	ENTRANCE DOOR, HOLLOW METAL	HOLLOW CUSTOM FABRICATED HOLLOW METAL EXTERIOR DOOR IN EXISTING FRAMED OPENING	TO MATCH EXISTING, APPROX. 2'-8" X 6'-3"	EXISTING STEEL/IRON FRAME TO REMAIN (STRIP AND RE-PAINT). REPLACE WOOD SILL MEMBERS WITH MAHOGANY TO MATCH EXISTING	HIGH-PERFORMANCE COATING, EXTERIOR SIDE PER I-A-201, INTERIOR SIDE WHITE		CUSTOM FABRICATE DOOR TO MATCH SIZE AND SHAPE OF EXISTING. DRILL AND TAP EXISTING IRON FRAME FOR NEW HARDWARE.		
102	EXISTING BASEMENT DOOR, BUILT-UP PANEL	REFURBISH EXISTING	EXISTING TO REMAIN	EXISTING	PAINT				
301	INTERIOR WOOD PANEL DOOR	REPLACE WITH NEW WOOD DOOR MATCHING EXISTING MATERIALS AND CONSTRUCTION	TO MATCH EXISTING	EXISTING TO REMAIN	PAINT		VISION PANEL: 1/4" LAMINATED GLASS - CLEAR		
401	INTERIOR BUILT-UP WOOD PANEL DOOR	FABRICATE AND INSTALL WOOD PANEL DOOR IN EXISTING WOOD FRAME	TO MATCH EXISTING DOOR OPENING, APPROX 2'-6" X 6'-4" X   3/4"	EXISTING	PAINT	7-A-301			
501	EXTERIOR DOOR TO WATCH DECK, HOLLOW METAL	CUSTOM FABRICATED HOLLOW METAL EXTERIOR DOOR AND BUILT-UP STEEL PLATE FRAME	SIZE PER EXISTING WALL PANEL OPENING (APPROXIMATELY 2'-0" X 6'-6") x I 3/4" THICK	BUILT-UP STEEL PLATE MEMBERS AS DETAILED	HIGH-PERFORMANCE COATING, EXTERIOR SIDE PER I-A-201, INTERIOR SIDE WHITE	5-A-303, 6-A-303			
601	EXTERIOR CAST IRON DOOR TO LANTERN DECK	EXISTING TO REMAIN AND BE REFINISHED	EXISTING TO REMAIN	REPAIR EXISTING WOOD FRAME TO ORIGINAL CONDITION AND APPEARANCE	HIGH-PERFORMANCE COATING, ALL SIDES PER I-A-201				

REFER TO SPECIFICATIONS FOR HARDWARE FOR EACH DOOR



REVISION

REVISION DATE MADE APP'D BY BY

STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522 Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580

Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY **DETAILS** 


DRAWING TITLE:


A-3	303
CONTRACT NUMBER:	DPW DRAWING NUMBER:
21-516	8-12-A-37
SHEET NO.: 0	9 of 23


DRAWING NUMBER:


DETAILS


scale: as noted DATE: 08-20-2021 DPW FILE NO. 8-12-A-37











CONSULTANT SEAL

STEPHEN TILLY, Architect
22 Elm Street, Dobbs Ferry, New York 10522
Structural Engineer: Structures North Consulting Engineers, Inc.
60 Washington St., Suite 401, Salem, MA 01970

60 Washington St., Suite 401, Salem, MA 01970

MEP Engineer: Tietjen Venegas Conulting Engineers
68 Purchase Street, Rye, New York 10580

Cathodic Protection Consultant: Echem Consultants, LLC
4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER: S201

CONTRACT DPW DRAWING NUMBER: NUMBER:

STRUCTURAL PLANS, SECTIONS

& DETAILS

WESTCHESTER COUNTY, NEW YORK
DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION
DIVISION OF ENGINEERING


TARRYTOWN LIGHTHOUSE RESTORATION
KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY
STRUCTURAL PLANS & DETAILS

21-516 8-12-S-39

SHEET NO.: 11 of 23

SCALE: QS noted
DATE: 08-20-2021

DPW FILE NO. REV. NO.
8-12-S-39



## GENERAL NOTES

- 1. ALL WORK SHALL COMPLY WITH THE STATE'S ADOPTED NFPA AND ADOPTED NEC WITH LOCAL SUPPLEMENTS.
- 2. WORK PERFORMED SHALL BE UNDERTAKEN WITH PRECAUTION BEING MAINTAINED TO ENSURE SAFETY OF PERSONNEL AND EQUIPMENT IN AREA IN SUCH A MANNER SO AS NOT TO DISTURB NORMAL WORK PROCEDURE.
- 3. WORK SHOWN IS DIAGRAMMATIC. EXACT LOCATION OF CONDUIT RUNS SHALL BE DETERMINED IN FIELD. LOCATE NEW CONDUIT RUNS TO CLEAR EXISTING AND NEW PIPING. DUCTWORK. ACCESS DOORS AND OTHER OBSTRUCTIONS. COORDINATE CONDUIT ROUTING WITH WORK OF OTHER TRADES AND ALTER WHERE NECESSARY TO AVOID INTERFERENCE. LOCATIONS OF RUNS AND EQUIPMENT TO BE APPROVED BY ARCHITECT IN FIELD PRIOR TO COMMENCING. SHOP DRAWINGS SHALL INCLUDE WIRING. PULLBOXES, JUNCTION BOXES, FITTINGS, WIRING DEVICES, CONTROL DEVICES AND DIMENSIONED CLEARANCES FROM EXISTING STRUCTURE AND EQUIPMENT. COORDINATE SHOP DRAWINGS WITH OTHER TRADES PRIOR TO
- 4. PROVIDE IDENTIFICATION TAGS FOR NEW WIRING AND INSTALL AT EACH END AND IN INTERMEDIATE PULL/JUNCTION BOXES, CABINETS, HOUSINGS, ETC. INDICATE ON TAGS, LEGIBLY, MINIMUM 1/4" HIGH LETTERS, THE POINTS OF ORIGIN AND TERMINATION OF EACH CIRCUIT. INCLUDE DATE OF INSTALLATION.
- 5. WHEN PORTION OF AN EXISTING CIRCUIT IS TO BE REMOVED OR IS ON WALL BEING REMOVED, CONTRACTOR SHALL MAKE NECESSARY MODIFICATIONS AND/OR ADDITIONS REQUIRED TO MAINTAIN CIRCUIT CONTINUITY OF UNCHANGED PORTION.
- 6. VERIFY EXACT LOCATION OF EQUIPMENT, SHOWN OR NOT SHOWN, IN FIELD PRIOR TO PERFORMING ANY WORK.
- 7. VERIFY IN FIELD THAT ANY EQUIPMENT AND WIRING TO BE REMOVED DOES NOT SERVE ACTIVE EQUIPMENT TO REMAIN PRIOR TO DISCONNECTING/
- 8. INSTALL CONDUIT RUNS AS CLOSE TO CEILING DECK AS POSSIBLE. PROVIDE REQUIRED CONDULETS, ELBOWS, FITTINGS, OFFSETS, AND PULLBOXES.
- 9. CONDUITS SHALL BE PROPERLY SUPPORTED FROM CEILING DECK ABOVE. NO CONDUIT SHALL BE SECURED TO, SUPPORTED BY OR HUNG FROM DUCTWORK OR PIPING OR OTHER SUCH ITEMS.
- 10. WORK REQUIRING SHUT-DOWN OF ELECTRIC SERVICE SHALL BE PERFORMED DURING PRE-SCHEDULED SHUT-DOWN AS SCHEDULED AND APPROVED BY ARCHITECT. INCLUDE COSTS IN BID.
- 11. NEW WORK SHALL BE COMPATIBLE WITH EXISTING SYSTEM AND EQUIPMENT. 12. PROVIDE CUTTING AND PATCHING REQUIRED FOR ELECTRICAL INSTALLATION.
- 13. PROVIDE SLEEVES FOR RACEWAYS PIERCING FIRE RATED WALLS, FLOORS, AND OTHER CONSTRUCTION OBSTACLES. 14. MATERIALS REMOVED BY CONTRACTOR AND NOT REQUIRED FOR INSTALLATION

SHALL BE REMOVED FROM PREMISES AND DISPOSED OF IN LEGAL

MANNER, IMMEDIATELY WHEN SO DIRECTED BY ARCHITECT.

- 15. APPLY LABELING ON CONDUIT FOR BUILDING ALARM CIRCUITRY AT INTERVALS
- 16. CONDUCTORS IN PARALLEL SHALL BE INSTALLED IN STRICT ACCORDANCE
- WITH APPLICABLE CODES. 17. PHASING OF ELECTRICAL WORK SHALL COMPLY WITH "PHASING OF THE WORK" AS DESCRIBED BY ARCHITECT.
- 18. PROVIDE BLANK COVERS ON ABANDONED OR UNUSED OUTLET BOXES.
- 19. MAKE FINAL CONNECTIONS FOR MOTORIZED EQUIPMENT OR EQUIP. SUBJECT TO VIBRATION, WITH FLEXIBLE RACEWAY.
- 20. IF ANY DEVIATIONS/VARIATIONS ARE DISCOVERED BETWEEN FLOOR PLANS AND CONNECTION DIAGRAMS, THE CONTRACTOR SHALL PROVIDE FOR THE MOST EXPENSIVE SITUATION WITH CREDIT SUBMITTED, SHOULD THE LESSER AMOUNT BE REQUIRED.
- 21. WHERE THE PLANS DO NOT INDICATE THE BRANCH CIRCUIT WIRING AND CONDUIT FOR FIXTURES OR OUTLETS NOR THE CONDUIT SIZE FOR FEEDERS. PROVIDE THE CORRECT WIRING QUANTITY AND SIZE, INSTALLED IN CONDUIT, AS REQUIRED BY THE INDICATED CIRCUITRY AND THE NATIONAL ELECTRICAL CODE WITH LOCAL SUPPLEMENTS.
- 22. PROVIDE IDENTIFICATION ON EACH FACEPLATE, DISCONNECT SWITCH, PANEL, ETC. IDENTIFICATION OF WIRING DEVICE FACEPLATE SHALL CONSIST OF PANEL DESIGNATION AND CIRCUIT NUMBER OF DEVICE AS CONNECTED. UTILIZE BROTHER 'P-TOUCH' TYPE MATERIAL ADHERED TO FACEPLATE.
- 23. NEW SYSTEMS SHALL BE MADE OPERATIONAL AS RENOVATED SPACES ARE ACCEPTED, PROVIDE PERSONNEL, TESTING, SCHEDULING AS REQUIRED. INCLUDE COST IN BID.
- 24. LOCATIONS OF OUTLETS ARE APPROXIMATE AND FINAL LOCATION SHALL BE AS DIRECTED BY THE ARCHITECT. VERIFY ALL LOCATIONS BEFORE INSTALLATION. NO EXTRAS WILL BE ALLOWED FOR CHANGES UP TO 10'-0" FROM LOCATION SHOWN ON PLAN PRIOR TO ROUGH-IN.
- 25. CIRCUIT NUMBERS ON THE DRAWINGS ARE FOR IDENTIFICATION ONLY AND DO NOT INDICATE THE POSITION ON THE PANEL BOARD. CONNECT THE CIRCUITS WITH THE LIGHTEST LOADS AND THE RECEPTACLE CIRCUITS NEAR THE TOP OF THE PANEL AND THE MORE HEAVILY LOADED CIRCUITS NEAR THE BOTTOM. BALANCE ALL CIRCUITS EVENLY BETWEEN PHASES SO THAT FEEDER WIRES CARRY APPROXIMATELY EQUAL CURRENT. REBALANCE IF
- 26. IN GRADE WORK. PROVIDE PULL BOXES WITH TRAFFIC RATED COVER. EXACT LOCATION TO BE COORDINATED IN FIELD.

## RACEWAY NOTES

#### <u>CONDUCTORS</u>

- -INTERIOR, COPPER, THWN, 600V, #12 MINIMUM #12, #10 SOLID, ALL LARGER STRANDED.
- -EXTERIOR, COPPER XHHW, 600V #12, #10, SOLID, ALL LARGER STRANDED.

- -INTERIOR (CONCEALED) MOISTURE RESISTANT MC CABLE, ALUMINUM JACKET, COPPER, THWN CONDUCTORS.
- -INTERIOR (EXPOSED) RIGID ALUMINUM CONDUIT WITH THREADED FITTINGS. -EXTERIOR (ABOVE GRADE), RIGID ALUMINUM CONDUIT WITH THREADED FITTINGS.
- -EXTERIOR (BELOW GRADE), SCHEDULE 80 PVC WITH METAL ELBOWS.
- -INTERIOR, CAST ALUMINUM. STAMPED METAL NOT PERMITTED.
- -EXTERIOR, NEMA 4X, STAINLESS STEEL, WITH GASKETS.

PROVIDE ANTI-OXIDENT COATING ON ALL CONNECTIONS THROUGH AND TO EXISTING BUILDING, STEEL.

		LIGHTI	N G F I X T	URE S	S C H	I E D	ULE
FIXTURE TYPE	SYMBOL	DESCRIPTION	MFG. CATALOG NO.	LAMP DATA INFO.	VOLTAGE	MOUNTING	REMARKS
(FI)		EXTERIOR BRIDGE NAVIGATION LIGHT	BASELITE # PRD-1-PR3-CG-49-10W(3000K LED)	10W, LED, 3000K	120V	PIER	
<b>F</b> 2	ф-	EXTERIOR BOLLARD LIGHT 43" HIGH, 7"DIAM	BASELITE #BOL15-PR3-49-150W(INC)	LED, 2700K, 8.5W BULBRITE #776613	120V	BOLLARD	PROVIDE FOUNDATION
<b>F</b> 3	ф	EXTERIOR WALL LIGHT	BASELIGHT # BW1-PR3-22-INC	LED, 2700K, 8.5W BULBRITE #776613	120V	WALL	PROVIDE CAST BACK BOX
<b>(F4)</b>	ф	CAST ALUMINUM INTERIOR FIXTURE WITH JBOX	DAYBRITE # VIN100I12-GG-VINW-JB50	LED, 2700K, 8.5W BULBRITE #776613	120V	WALL	
<b>(F5)</b>	<b>-</b>	CAST ALUMINUM INTERIOR FIXTURE. CEILING MOUNT WITH JBOX	DAYBRITE # VIN100I12-RGG-VINC50	LED, 2700K 8.5W BULBRITE #776613	120V	CEILING	
<b>(F6)</b>	EM	TWO HEAD EM PACK. BASEMENT ONLY NEMA 4X	DUAL-LITE-DYNOMO-NEMA 4X-DYN-6-4X-HTR	3 WATT LED AS SUPPLIED	120V	WALL	BASEMENT ONLY
€	<u> </u>	EXTERIOR, LOWER WASH LIGHTING CAST ALUMINUM	HYDREL #4750L-4-500LMF- 30K-MV-NSP-KMJ-27-MRE-BL	LED, 3000K, 2000LM, 80W	120V	WALL/ WALKWAY	PROVIDE NIGHT-TIME AIMING SESSION WITH ARCHITECT PROVIDE MOUNTING HARDWARE PROVIDE CIRCUITRY FOR 0-10V DIMMING
<b>(F8)</b>	ď	EXTERIOR, UPPER WASH LIGHTING CAST ALUMINUM 360° KNUCKLE	BKLIGHTING #DENALI LED# DE-LED-TR-X99-WFL-12-A-ELV	LED, 3000K, 869LM, 13W	120V	WALL/ WALKWAY	PROVIDE NIGHT-TIME AIMING SESSION WITH ARCHITECT PROVIDE MOUNTING HARDWARE PROVIDE CIRCUITRY FOR ELV DIMMING

2. SUBMIT D.O.E. LIGHTING FACT SHEET FOR ALL FIXTURES

MADE APP'D

BY

BY

REVISION


REVISION

NUMBER


DATE


AND APPROVED SHOP DRAWINGS. VERIFY CEILING TYPES, PRIOR TO SUBMITTING FIXTURES. 3. PROVIDE FIXTURES WITH NECESSARY TRIM & ACCESSORIES REQUIRED FOR A COMPLETE INSTALLATION. 5. COLOR & FINISHES SHALL BE AS SELECTED BY ARCHITECT.


	BACKFILL TO GRADE RESTORE SURFACE.	<sub>C</sub> EXISTING GRADE
UNEXCAVATED  24" MIN TO TOP  OF FEEDER RUN		-COMPACTED AND SCREENED BACKFILL -REMOTE SENSING TAPE
1. SEE POWER ONE LINE DIAGRAM AND PANEL SCHEDULES FOR SIZE & QUANTITY. COORDINATE WITH ALTERNATES AS SELECTED.		-2" MINIMUM POURED CONCRETE COVER IN TRAFFIC AREAS AND ALL AREAS FOR ELECTRIC SERVICE6" SAND BACKFILL UNDER CONDUITS -PVC SCHEDULE 80 CONDUIT (POWER)
2. ALL LABOR AND MATERIAL BY EC.		PVC SCHEDULE 80 CONDUIT (SIGNAL)
<ol><li>CLEAN SCREENED BACKFILL, NO ROCKS OVER 3" IN ANY DIMENSION</li></ol>		
4. MAINTAIN 12" SEPARATION BETWEEN SIGNAL AND POWER		



	ELECTRIC LEGEND					
SYMBOL	DESCRIPTION &/OR SPECIFICATION					
#	DUPLEX RECEPTACLE, 20AMP TAMPER RESISTANT, LEVITON #TCR20-COLOR					
GF <del>◯</del>	DUPLEX GROUND FAULT RECEPTACLE - 20 AMP TAMPER RESISTANT LEVITON # GFWT2-65362-WT-COLOR					
4	DISCONNECT SWITCH					
WP	WEATHER PROOF, RANTITE-WHILE-IN-USE					
	LIGHTING PANEL					
	CONDUIT RUN (NEW)					
J	JUNCTION BOX					
<b></b>	WORK ITEM					
ф 	SEE LIGHT FIXTURE SCHEDULE FOR LIGHT FIXTURE TYPE					
S	20 AMP TOGGLE SWITCH LEVITON 54522-W					
	EXISTING					
++++++	TO BE REMOVED					









# 22 Elm Street, Dobbs Ferry, New York 10522 tructural Engineer: Structures North Consulting Engineers, Inc.

60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER:

CONTRACT | DPW DRAWING

NUMBER:

SITE PLAN, RISER


DETAIL, NOTES


NUMBER:




TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY ELECTRICAL - SITE PLAN, RISER, DETAIL, NOTES

21-516 |8-12-E-4 SHEET NO.: **13** OF 23 scale: as noted DATE: 08.20.2021 DPW FILE NO. 8-12-E-**41** 









STEPHEN TILLY, Architect
22 Elm Street, Dobbs Ferry, New York 10522
Structural Engineer: Structures North Consulting Engineers, Inc.
60 Washington St., Suite 401, Salem, MA 01970

MEP Engineer: Tietjen Venegas Conulting Engineers
68 Purchase Street, Rye, New York 10580

Cathodic Protection Consultant: Echem Consultants, LLC
4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER:

ELECTRICAL

ELEVATION

DRAWING TITLE:

WESTCHESTER COUNTY, NEW YORK
DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION
DIVISION OF ENGINEERING

TARRYTOWN LIGHTHOUSE RESTORATION
KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, N
ELECTRICAL - ELEVATION

YORK	CONTRACT NUMBER:	DPW DRAWING NUMBER:
ORTATION	21-516	8-12-E- <b>44</b>
	SHEET NO.:	<b>16</b> OF 23
	SCALE: as r DATE: 08.20.2	
LOW, NY	DPW FILE NO.	REV. NO.
	8-12-E	-44   <sub>0</sub>

REVISION DATE MADE BY BY REVISION

#### GENERAL NOTES

#### CATHODIC PROTECTION

- 1. ALL WORK IS TO BE CARRIED OUT IN ACCORDANCE WITH DIVISION 3 SPECIFICATION FOR CONCRETE, DIVISION 18 SPECIFICATION FOR CATHODIC PROTECTION (CP), DIVISION 26 LOW VOLTAGE ELECTRICAL, AND ANY OTHER REQUIRED WORK SCOPES NOT REFERENCED HEREIN.
- 2. FOLLOW ALL PROCEDURES OUTLINED IN THE SPECIFICATIONS. IF THERE IS A DISCREPANCY BETWEEN WORK ITEMS, DEFER TO THE MORE COMPLETE WORK SCOPE.
- 3. PROVIDE DOCUMENTATION REQUIRED WITHIN SECTION 180200, ITEM 3.17 SUBMITTALS BEFORE STARTING WORK.
- 4. THE USE OF CATHODIC PROTECTION DRAWINGS SHOULD BE USED FOR GUIDANCE ONLY. LOCATION OF ALL EMBEDDED ITEMS ARE INDICATIVE. EXACT LOCATIONS WILL BE DICTATED BY SITE CONDITIONS.
- 5. THE USE OF CATHODIC PROTECTION IS INTENDED TO PROTECT THE BACK OF THE CAST IRON CAISSON PLATING FROM CORROSION AT THE FOUR ZONE LOCATIONS AS INDICATED IN THE ZONE LAYOUT DRAWINGS.
- 6. FOLLOW ALL TESTING PROCEDURES OUTLINED WITHIN THE SPECIFICATION OF WORK WITHIN SECTION 180200 TO ENSURE SYSTEM IS FUNCTIONAL.
- 7. PROVIDE ALL TEST DATA AND REQUIRED RECORDS OUTLINED IN SECTION 180200, ITEM 1.08 -DOCUMENTATION.
- 8. DOCUMENTATION SHALL BE AVAILABLE ONSITE AT ALL TIMES. WEEKLY SUBMISSIONS SHALL BE SUBMITTED TO DESIGN TEAM FOR REVIEW AND ACCEPTANCE.

#### ANODE ZONES

9. THIS PROJECT CONSISTS OF A FOUR (4) ZONE CATHODIC PROTECTION SYSTEM. A ZONE IS DEFINED AS AN AREA HAVING AN INDEPENDENT DC POWER SOURCE.

10. THE FOUR (4) ZONES ARE LAID OUT AS FOLLOWS:

- 10.1. ZONE 1 NORTHWEST QUADRANT
- 10.2. ZONE 2 NORTHEAST QUADRANT
- 10.3. ZONE 3 SOUTHEAST QUADRANT
- 10.4. ZONE 4 SOUTHWEST QUADRANT

#### CONTINUITY TESTING

- 11. THE CONTRACTOR SHALL CONFIRM THAT ALL EMBEDDED METALS WITHIN EACH ANODE ZONE IS ELECTRICALLY CONTINUOUS. THE METALLIC ELEMENTS WITHIN THE STRUCTURE SHALL BE BONDED FOR CONTINUITY IF REQUIRED. THIS SHALL BE DEMONSTRATED ON SITE BY MEASURING THE ELECTRICAL RESISTANCE BETWEEN THE SECTIONS IN LOCATIONS REMOTE FROM ONE ANOTHER ACROSS THE STRUCTURE AND AT ALL LOCATIONS WHERE THE METAL IS EXPOSED. THIS SHALL INCLUDE AT A
- 11.1. ELECTRICAL CONTINUITY BETWEEN ELEMENTS OF THE STRUCTURE WITHIN EACH ZONE OF CATHODIC PROTECTION.
- 11.2. ELECTRICAL CONTINUITY OF THE EMBEDDED STEEL / IRON WITHIN ELEMENTS OF THE STRUCTURE.
- 11.3. ELECTRICAL CONTINUITY OF METALLIC ITEMS, OTHER THAN THE STEEL, IN THE CONCRETE OR LIGHTHOUSE WALL WHICH MAY BE AFFECTED BY STRAY CURRENT.
- 11.4. ANCHORS OR METALLIC ITEMS EXPOSED DURING THE INSTALLATION OF THE CP SYSTEM.
- 11.5. CONFIRMATION THAT THE MISCELLANEOUS METALLIC ITEMS ARE CONTINUOUS PRIOR TO ENERGIZATION OF THE SYSTEM.
- 12. ALL ELECTRICAL CONTINUITY SHALL BE CARRIED OUT IN ACCORDANCE WITH SECTION 180200, ITEM 3.04 CONTINUITY TESTING.
- 13. THE ACCEPTANCE CRITERIA FOR CONTINUITY SHALL CONSIST OF:
- 13.1. STABLE VALUES WITH RESISTANCE MEASUREMENTS LESS THAN 1.0 OHM.
- 14. CONTINUITY RECORDS SHALL BE KEPT OF ALL TESTS CARRIED OUT AND SHALL BE SUBMITTED TO THE OWNER IN THE FORM OF A CONTINUITY CERTIFICATE.

## ANODE SYSTEM

- 15. THE ANODE SYSTEM SHALL BE INSTALLED IN ACCORDANCE WITH SECTION 180200, ITEM 3.06 ANODE SYSTEM AND IN ACCORDANCE WITH THE DRAWINGS.
- 16. THE CONTRACTOR SHALL SUBMIT A METHOD STATEMENT AS PART OF THE CATHODIC PROTECTION PRE-START REPORT TO DETAIL THE SYSTEM.
- 17. ALL ZONES SHALL BE COMPRISED OF MIXED METAL OXIDE (MMO) SINTERED TITANIUM RIBBON ANODE CHAINS SPOT WELDED TO CONDUCTOR BAR AS SEEN IN DETAIL 1 ON XXO3.
- 18. EACH ANODE IS TO BE INSTALLED IN A PRE-CORED HOLE OF SET DEPTH DEPENDENT UPON THE SPECIFIC REQUIREMENTS AS DETAILED WITHIN THE CONSTRUCTION DRAWINGS AND VERIFIED BY THE CONTRACTOR.
- 19. ANODE GROUT WILL BE COMPRISED OF CEMENTITIOUS MATERIAL MIX DESIGN COMPATIBLE WITH THE ORIGINAL CONCRETE BASED ON LABORATORY ANALYSIS.
- 20. THE SPECIFIED NUMBER OF ANODES IS PROVIDED ON THE ANODE LAYOUT DRAWING ON XX06.

#### CATHODE SYSTEM

- 21. THE NUMBER AND APPROXIMATE LOCATIONS OF EACH OF THE SYSTEM NEGATIVES IS DETAILED ON THE CONSTRUCTION DRAWINGS. THE CATHODE SYSTEM AT EACH ANODE ZONE SHALL PROVIDE A MINIMUM OF TWO (2) CABLE CONNECTIONS TO THE CAST IRON CAISSON.
- 22. TWO (2) CONNECTIONS SHALL BE MADE FOR THE MONITORING CELLS (STEEL TEST) IN EACH ZONE; THE CABLES WILL BE INSTALLED AS INDIVIDUAL CABLES WITH THE INDEPENDENT TERMINATIONS AT THE POWER SUPPLY.

#### MONITORING SYSTEM

- 23. TWO (2) REFERENCE CELLS SHALL BE INSTALLED IN EACH ZONE, AS INDICATED IN THE SPECIFICATIONS AND DRAWINGS.
- 24. TWO (2) STEEL TESTS ARE TO BE INSTALLED IN EACH ZONE AS INDICATED IN THE SPECIFICATIONS AND DRAWINGS.
- 25. FIVE (5) CORROSION COUPONS ARE TO BE INSTALLED IN EACH ZONE AS INDICATED IN THE SPECIFICATIONS AND DRAWINGS.

#### CONTINUITY BONDING

- 26. ALL NECESSARY BONDING AND OR REMOVAL OF DISCONTINUOUS METALLIC ELEMENTS SHALL BE CARRIED OUT IN ACCORDANCE WITH SECTION 180200, ITEM 3.05 - CATHODE CONNECTIONS.
- 27. CARRY OUT STRAY CURRENT TESTING IN ACCORDANCE WITH SECTION 180200, ITEM 3.13 STRAY CURRENT TESTING SHOULD THERE BE CONCERNS A DISCONTINUOUS METALLIC ELEMENT IS AT RISK OF STRAY CURRENT OR IF THE ELEMENT IS AT THE PERIMETER OF THE ANODE ZONE OF INFLUENCE.



STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522 Structural Engineer: Structures North Consulting Engineers, Inc.

60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

CATHODIC PROTECTION-GENERAL NOTES

DRAWING TITLE:

CHESTER COUNTY, NEW YORK ENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

> TARRYTOWN LIGHTHOUSE RESTORATION ND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY CATHODIC PROTECTION - GENERAL NOTES

21-516 8-12-E-45 SHEET NO.: 17 OF 23 SCALE: as noted DATE: 08-20-2021 DPW FILE NO.

8-12-E -45

NUMBER:

CONTRACT DPW DRAWING

NUMBER:


3.6546.5					
WESTC					
DEPARTME					
-					
KINGSLAND					
CA	REVISION	APP'D BY	MADE BY	DATE	REVISION NUMBER

DRAWING NUMBER:

# ZONE ZONE 2 LEGEND ZONE 1 ZONE 2 ZONE 3 ZONE 4 ZONE ZONE LAYOUT

## NOTES:


- 1. FINAL MCU LOCATION TO BE DETERMINED ON SITE WITH THE DESIGN TEAM AND CATHODIC PROTECTION SUPERVISOR/MANAGER.
- 2. THROUGH WALL PENETRATIONS REQUIRED AS SHOWN ON THE ASSOCIATED DRAWINGS.
- 3. THROUGH WALL WIRING TO BE PROTECTED AT THROUGH WALL HOLE BY BEING PLACED IN 1" RIGID PVC CONDUIT SCHEDULE 80.
- 4. THROUGH WALL PIPE TO ENTER 2" OR MORE BELOW THE JUNCTION BOX TO ALLOW FOR A RIGHT-ANGLE ELBOW TO BE UTILIZED FOR CABLE DISTRIBUTION TO THE JUNCTION BOX.
- 5. ALL CONDUIT ROUTED FROM THE JUNCTION BOXES TO THE MCU SHALL BE A MINIMUM OF 1" TYPE 316 FLEXIBLE METAL STAINLESS STEEL TUBING UNLESS OTHERWISE SPECIFIED.
- 6. IF JUNCTION BOX IS PLACED ON INTERIOR WALL WITHIN THE ANODE ZONE OF INFLUENCE USE NON-METALLIC ANCHORAGE TO SECURE JUNCTION BOX TO WALL.





ELECTRICAL LAYOUT

REVISION DATE



#### STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522

Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER:

DRAWING TITLE:

CATHODIC


PROTECTION-ICCP


LAYOUT

SHEET NO.: 18 OF 23

CONTRACT DPW DRAWING NUMBER: NUMBER: YORK 21-516 8-12-E -46


SCALE: as noted DATE: 08-20-2021 DPW FILE NO. 8-12-E -46 CATHODIC PROTECTION - ICCP LAYOUT





PARTS LIST							
ITEM	QTY	PART NUMBER	DESCRIPTION				
1	1	ISO7045-M5x12-4.8-H	PAN HEAD SCREW WITH TYPE H CROSS RECESS				
2	1	IS07089-5-140 HV	PLAIN WASHERS- PRODUCT GRADE A				
3	1	ASME B18.21.2M-5	LOCK WASHERS (METRIC SERIES)				


SCREWS AND WASHERS REFERENCE ELECTRODE DETAIL SCALE: NTS




CORROSION COUPON DETAIL SCALE: NTS


HEATSHRINK & SOLDER RING TERMINAL.

ANODE RIBBON DETAIL



CATHODE CONNECTION





ANODE INSTALLATION WITH REFERENCE ELECTRODE SCALE: NTS

1. TOP 12" OF CONCRETE SLAB TO BE REMOVED PRIOR TO THE INSTALLATION OF THE CP SYSTEM. COORDINATE WITH DIVISION 3 AND STRUCTURAL ARCHITECTURE SCOPE.

2. ALL CONNECTION LOCATIONS ARE CALLED OUT ON XX07.

3. TUBULAR ANODE CHAIN CONSISTS OF MMO TITANIUM RIBBON SPOT WELDED TO TITANIUM CONDUCTOR BAR AS SEEN IN DETAIL 1.

4. ANODES TO BE PLACES IN ACCORDANCE WITH DESIGN REQUIREMENTS INDICATED ON XX06 AND ILLUSTRATED ON XX03.

5. USE BEST PRACTICES AND JUDGEMENT WHEN PLACING ANODES.

CATHODE CONNECTIONS / STEEL TESTS

6. MAKE CATHODE / STEEL TEST CONNECTIONS IN ACCORDANCE WITH SECTION 180200, ITEM 3.05 - CATHODE CONNECTIONS.

7. UTILIZE DETAIL 2 CATHODE CONNECTION FOR STEEL TEST CONNECTIONS ASSOCIATED WITH REFERENCE ELECTRODES.

8. ENSURE THAT SELF-THREADED SCREW IS FULLY ENCAPSULATED IN NON-CONDUCTIVE EPOXY.

9. DO NOT SPLICE OR COMMON STEEL TEST CONNECTION.


REFERENCE ELECTRODES / CORROSION COUPON

10. INSTALL Ag/AgKCI (0.5M) REFERENCE ELECTRODES AND CORROSION COUPONS IN ACCORDANCE WITH SECTION 180200.

11. POSITION THE REFERENCE ELECTRODE SUCH THAT THE 3.5mm HOLE AT THE SIDE OF THE ELECTRODE FACES THE CAST IRON CAISSON AND DOES NOT POINT TOWARDS AN ANODE.

12. REFERENCE ELECTRODE / CORROSION COUPON WIRES SHALL NOT TO BE SPLICED PRIOR TO ENTERING A TERMINATION BOX..

13. REFERENCE ELECTRODES AND CORROSION COUPONS SHALL BE SECURELY FASTENED TO THE CONDUCTOR BAR WITH NON-METALLIC TIES.



ANODE INSTALLATION WITH CORROSION COUPON SCALE: NTS

MADE APP'D BY BY

REVISION

REVISION DATE

HALAR®/HMWPE

APPROVED

LG 25 Ag/AgKCI REFERENCE ELECTRODE



STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522

Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers

68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY CATHODIC PROTECTION - SYSTEM COMPONENT DETAILS

DRAWING NUMBER: CONTRACT DPW DRAWING NUMBER: NUMBER: 21-516 8-12-E -47

DRAWING TITLE:


CATHODIC


PROTECTION-SYSTEM

COMPONENT


**DETAILS** 

SHEET NO.: 19 OF 23 SCALE: as noted DATE: 08-20-2021 DPW FILE NO. 8-12-E -47





JUNCTION BOX DETAIL



OTHERWISE SPECIFIED.

1. FINAL MCU LOCATION TO BE DETERMINED ON SITE WITH THE DESIGN TEAM AND CATHODIC PROTECTION

2. JUNCTION BOX TO BE CONSTRUCTED OF COMPRESSION MOLDED GLASS REINFORCED POLYESTER, NEMA 4X, 4A IP67 BSEN 50019/50021 AND COLORED TO RAL 7000 (DARK GREY).

3. ALL GLANDS AND CONNECTIONS SHALL BE IP68 RATED AND COMPATIBLE WITH FMSST.

4. THROUGH WALL PIPE TO ENTER 2" OR MORE BELOW THE JUNCTION BOX TO ALLOW FOR A

RIGHT-ANGLE ELBOW TO BE UTILIZED FOR CABLE DISTRIBUTION TO THE JUNCTION BOX. 5. ALL CONDUIT SHALL BE A MINIMUM OF 1" TYPE 316 FLEXIBLE METAL STAINLESS STEEL TUBING UNLESS

6. IF JUNCTION BOX IS PLACED ON INTERIOR WALL WITHIN THE ANODE ZONE OF INFLUENCE USE NON-METALLIC ANCHORAGE TO SECURE JUNCTION BOX TO WALL.

- MALE ADAPTER 90° INSPECTION ELBOW


JUNCTION BOX CONDUIT DETAIL SCALE: NTS

DATE

NUMBER

MADE APP'D BY BY

REVISION



#### STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522

Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC

4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER:

DRAWING TITLE:

CATHODIC

PROTECTION-POWER


SUPPLY DETAILS

CONTRACT DPW DRAWING NUMBER: NUMBER: 21-516 8-12-E-48

WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

SHEET NO.: 20 OF 23 SCALE: as noted DATE: 08-20-2021 DPW FILE NO. 8-12-E-48

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY CATHODOC PROTECTION - POWER SUPPLY DETAILS



WIRING DIAGRAM

NOTES:

- 1. ALL CABLE SIZES SHALL BE 14AWG UNLESS OTHERWISE SPECIFIED.
- 2. ALL NEGATIVE FIELD CONNECTIONS WITHIN A ZONE ARE DAISY CHAINED TOGETHER WITH TWO (2) FEEDS RETURNING TO THE POWER SUPPLY UNIT.
- 3. ALL DC POWER CABLING IS AS FOLLOWS: POSITIVE - RED

NEGATIVE - BLACK

4. ALL MONITORING CABLING IS AS FOLLOWS: REFERENCE ELECTRODE — BLUE

STEEL TEST - YELLOW

BOND / CORROSION COUPON - GREEN

CONSULTANT SEAL

MADE APP'D BY BY

REVISION

REVISION NUMBER DATE

STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522 Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970

MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

CONTRACT DPW DRAWING NUMBER: NUMBER:

WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

> DPW FILE NO. 8-12-E-49

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY CATHODIC PROTECTION - WIRING DIAGRAM

8-12-E-49 21-516 SHEET NO.: 21 OF 23 SCALE: as noted DATE: 08-20-2021


DRAWING TITLE:

CATHODIC

PROTECTION-WIRING


DIAGRAM

DRAWING NUMBER:



- THE CATHODIC PROTECTION ANODE ZONE PROTECTS THE BACK FACE OF THE CAST IRON CAISSON AS DETAILED IN THE DESIGN TABLE ON THIS DRAWING.
- 2. EACH ANODE ZONE SHALL BE COMPRISED OF MMO TITANIUM RIBBONS SPOT WELDED TO TITANIUM CONDUCTOR BAR AS SHOWN IN DETAIL 1 ON XXO3.
- 3. ALL ANODES SHALL BE INSTALLED AT SPACING DETAILED ON DESIGN TABLE, ON CENTER, ±2".
- 4. HOLE DEPTH FOR ANODES SHALL BE CORED ACCORDING TO DETAILS ON XXO3.

	DESIGN TABLE							
ZONE	ANODES	# OF ANODES	ANODE LINES	ANODE SIZE	SPACING ±6"	TOTAL CURRENT (mA)		
1	A1-A7	7	1	10'	2'-9''	420.00		
2	A1-A7	7	1	10'	2'-9''	420.00		
3	A1-A7	7	1	10'	2'-9''	420.00		
4	A1-A7	7	1	10'	2'-9''	420.00		
		28				1680.00		



REVISION

REVISION DATE MADE APP'D BY BY

# STEPHEN TILLY, Architect

22 Elm Street, Dobbs Ferry, New York 10522
Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER:

DRAWING TITLE:

CATHODIC

PROTECTION-ANODE LAYOUT


CONTRACT DPW DRAWING NUMBER: NUMBER: WESTCHESTER COUNTY, NEW YORK **21–516** 8–12–E–50 DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION

CATHODIC PROTECTION - ANODE LAYOUT

SHEET NO.: 22 OF 23 SCALE: as noted DATE: 08-20-2021 DPW FILE NO.

8-12-E-50

DIVISION OF ENGINEERING											
TARRYTOWN LIGHTHOUSE RESTORATION											
KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY											



NOTES:
1. STEEL TESTS CABLE SHALL NOT BE COMMON TO CATHODE WIRES.

2. REFERENCE ELECTRODES AND STEEL TESTS ARE INDICATIVE ONLY, EXACT LOCATIONS SHALL BE FIELD

3. FOR WIRING DETAILS, REFER TO THE DIAGRAM ON XX05.

		ZONE 1 DES	SIGN TABLE		
ZONE	ANODES	# OF ANODES	ANODE LINES	ANODE SIZE	SPACING ±6"
1	P1-1	N1-1			CC1-1
	P1-2		R1-1	ST1-1	
	P1-3				CC1-2
	P1-4	N1-2			CC1-3
	P1-5		R1-2	ST1-2	CC1-4
	P1-6	1 111-2			
	P1-7				CC1-5
2	P2-1	N4-1			CC2-1
	P2-2		R2-1	ST2-1	
	P2-3				CC2-2
	P2-4	N4-2			CC2-3
	P2-5		R2-2	ST2-2	CC2-4
	P2-6				
	P2-7				CC2-5
3	P3-1	N3-1			CC3-1
	P3-2		R3-1	ST3-1	
	P3-3				CC3-2
	P3-4	N3-2			CC3-3
	P3-5		R3-2	ST3-2	CC3-4
	P3-6				
	P3-7				CC3-5
4	P4-1	N4-1			CC4-1
	P4-2		R4-1	ST4-1	
	P4-3				CC4-2
	P4-4				CC4-3
	P4-5	N4-2	R4-2	ST4-2	CC4-4
	P4-6				
	P4-7				CC4-5

CONSULTANT SEAL

REVISION NUMBER DATE

MADE APP'D BY BY

REVISION

STEPHEN TILLY, Architect 22 Elm Street, Dobbs Ferry, New York 10522

Structural Engineer: Structures North Consulting Engineers, Inc. 60 Washington St., Suite 401, Salem, MA 01970 MEP Engineer: Tietjen Venegas Conulting Engineers 68 Purchase Street, Rye, New York 10580 Cathodic Protection Consultant: Echem Consultants, LLC 4 Jefferson Plaza, Suite 500, Poughkeepsie, NY 12601

DRAWING NUMBER:

DRAWING TITLE:

CATHODIC

PROTECTION-ZONE

CONNECTIONS

CONTRACT DPW DRAWING NUMBER: NUMBER:

WESTCHESTER COUNTY, NEW YORK DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION DIVISION OF ENGINEERING

21-516 SHEET NO.: 23 OF 23 SCALE: as noted DATE: 08-20-2021

DPW FILE NO.

8-12-E-51

TARRYTOWN LIGHTHOUSE RESTORATION KINGSLAND POINT PARK, VILLAGE of SLEEPY HOLLOW, NY

CATHODIC PROTECTION - ZONE CONNECTIONS