

FIELD REPORT

REPORT DATE: 6/27/23

INSPECTION DATE: 6/26/23

LOCATION: Wilson Woods Pool

ORIGIN: Risk Management

RE: Inspection

BY: P. Gionta

An annual inspection of Wilson Woods Pool was conducted by Risk Management for the 2023 season. Grounds and buildings were reviewed as they relate to health, safety and liability.

Below are the issues found that require attention due to violation of fire code, OSHA/PESH code, County policy or otherwise industry recognized "best practice".

Concession Stand

-ANSUL system and fire extinguisher cert are 2 years expired

-Fire extinguisher needs to be wall mounted and not on the floor.

(I spoke with the vendor on above last season and they did not comply. I've told them once again it needs to be handled asap)

Lifeguard Station

-Fire extinguisher needs to be wall mounted and not on the floor.

Waterslide

Photos A

-Photos show the same railing front and back along the stairs up to and including the upper landing. The railing is loose and moves laterally 6-8 inches when handled. Vertical support members on outside are split at the connection hardware.

Photos B

-Pictures show the same joist end to end for the lower landing which is directly below the above pics and makes up the lower landing support. The joist is split lengthwise and is twisting away from the connection hardware.

Photo C

-Photo shows the right side railing at the lower landing.









Please feel free to contact Risk Management at 995-2706 with any questions on the listed issues. There are many resources available to County departments to facilitate occupational safety and violation abatement that Risk Management can provide.

FIELD REPORT

REPORT DATE: 06/27/23

INSPECTION DATE: 06/26/23

LOCATION: Sprain Ridge Pool/Park

ORIGIN: Risk Management

RE: Inspection

BY: P. Gionta

An annual inspection of Sprain Ridge Pool was conducted by Risk Management for the 2023 season. Grounds and buildings were reviewed as they relate to health, safety and liability.

Below are the issues found that require attention due to violation of fire code, OSHA/PESH code, County policy or otherwise industry recognized “best practice”

-No issues were found at the time of inspection.

Just some thoughts for discussion...

Each year the issues with the pool deck laser intrusion alarm comes up. Specifically, the frequent false alarms and the refusal of DPS to give PRC access to the cameras to see what is going on. As it was explained to me, the notifications of an alarm are sent to a few people with DPS being the last in line who then rely on PRC's OK to address it. They may or may not send a patrol car or communicate to PRC what is seen on their cameras.

I understand their reluctance to allow access to the police cameras but it seems there may be a sizable delay between the alarm tripping and a response; be it kids hopping the fence to go in the pool, a bird tripping the alarm or something more serious.

Would it be possible for PRC to install their own stand-alone web cam? Given the low cost, high quality and broad access options of consumer-grade web cams, I think it may be an easy solution. The orientation of the pools are such that it appears a single camera with zoom, pan and tilt could cover everything if mounted strategically.

If possible, I feel PRC really should have visual access. If we have a system in place that informs of this type of intrusion and its special hazards, it is incumbent upon us to have a proper and timely response.

Please feel free to contact Risk Management at 995-2706 with any questions on the listed issues. There are many resources available to County departments to facilitate occupational safety which Risk Management can provide.