Westchester County Department of Parks & Recreation Conservation

Facility:	Croton Point Park			
Work Order # <u>CPP-7-31-2022</u>				
Section: Cabin Ba	athroom Floor and Back Do	or	Budget Code	42-4100
Description of Work:	the shower area is on you are going to fall water stands and do	rack and rising. When y through its very soft. W	ou stand in front on the have been getting by. Also the back of th	d of repair. The tile floor around of the shower area its feel like ng complaints from patrons that door were the hot water heater o this email.
Date Work Required a	s soon as time permits		ient Funds Availab	ale: Vec
Estimated Cost:			ieni Funds Avallat	ole. res
Park Superintendent:	Ronald Anderson			Date: <u>7/31/2022</u>
Approved by Regional D	Director:		Priority:	1_Date:
JMOA □	Facility Inspection □	Fire Prevention Pr	ogram □ An	nual Fire Insp. Neil Caputo 🛚
Violation #	Violation #	Violation #	Vio	plation #
Approved by Director of	Operations	l Maintenance Use	·	ate
Referred to:			Date	
Date W.O. Inspected:			Pri	iority:
Facility Manager Notified	d:		Da	ate
Estimated Completion D	Date:			
Remarks:				
Date Work Started:			Date Work Comple	eted:
Work to be completed b	y facility:		Da	ate:
Work not required:				
□ Logged In				Completed