

Date: 03/21/2024

Facility: Glen Island

Location: Areas 11 & 12

I. GROUND HAZARD

No holes/depressions	X
No unsecured fences/gates	X
No exposed footings	X
No broken glass/litter	X
No poor drainage areas	X

II. SURFACING

Type: Wood Chips

Areas Need Surfaing/Raking: Yes Raking

III. EQUIPMENT: GENERAL

Smooth surfaces	X
Hardware in good condition	X
No entrapment/no angle	X
Capped ends	X
No sharp points, corners, edges, or loose welds	X
No protrusions	X
No projections	X
No pinch, crush, or shearing points	X
No tripping hazards	X
No suspended hazards (cables wires, ropes)	X
No equipment > 7 ft. high	X
Adequate surfacing	X
Litter can in good repair	X
Benches in good repair	X
Basketball nets OK	N/A
Park sign ok	N/A
No Over hanging limbs	X
Signs of vandalism	N/A
Park plantings OK	N/A

INSPECTOR

Name: Doug Falcone

Comments: Still waiting on parts for the bridge

IV. EQUIPMENT

SWINGS

S-hooks closed	N/A
Good chains/seats/hangers	N/A
No broken parts	N/A
Equipment stable	N/A
Adequate surfacing	N/A
Check chain wear	N/A
Pads under swings present	N/A

SLIDES

No loose steps or rails	X
Smooth surfaces	X
No loose screws/bolts	X
No broken parts	X
Adequate surfacing	X
Exit pads in place	X

PLAY STRUCTURES

Smooth surfaces	X
No metal rusts/wood rot	X
Stable/secure	X
No head entrapment	X
No loose handholds/rails	X
No loose nuts/bolts	X
No missing parts	X
No protrusions	X
Adequate lubrication	N/A
No worn/frayed cables	N/A
Adequate surfacing	X

CLIMBING APPARATUS

No cut ropes	N/A
No loose nuts/bolts	X
Secure anchor/footing	X
Smooth surfaces	X
Adequate handhold size	X
Adequate surfacing	X





WESTCHESTER COUNTY

WESTCHESTER COUNTY

DEPARTMENT OF PARKS, RECREATION & CONSERVATION

Weekly Playground Inspection Report

I. GROUND HAZARD	
No holes/depressions	<input checked="" type="checkbox"/>
No unsecured fences/gates	<input checked="" type="checkbox"/>
No exposed footings	<input checked="" type="checkbox"/>
No broken glass/litter	<input checked="" type="checkbox"/>
No poor drainage areas	<input checked="" type="checkbox"/>
II. SURFACING	
Type: <i>wood chips</i>	
Depth: <i>12</i>	
Areas Need Surfacing/Raking:	
III. EQUIPMENT: GENERAL	
Smooth surfaces	<input checked="" type="checkbox"/>
Hardware in good condition	<input checked="" type="checkbox"/>
No entrapment/no angle	<input checked="" type="checkbox"/>
Capped ends	<input checked="" type="checkbox"/>
No sharp points, corners, edges, or loose welds	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
No projections	<input checked="" type="checkbox"/>
No pinch, crush, or shearing points	<input checked="" type="checkbox"/>
No tripping hazards	<input checked="" type="checkbox"/>
No suspended hazards (cables wires, ropes)	<input checked="" type="checkbox"/>
No equipment > 7 ft. high	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Litter can in good repair	<input checked="" type="checkbox"/>
Benches in good repair	<input checked="" type="checkbox"/>
Basketball nets OK	<i>NA</i> <input type="checkbox"/>
Park sign ok	<input checked="" type="checkbox"/>
Over hanging limbs	<input checked="" type="checkbox"/>
Signs of vandalism	<input checked="" type="checkbox"/>
Park plantings OK	<input checked="" type="checkbox"/>
INSPECTOR	
Name: <i>Sara Cavanaugh</i>	
Comments: <i>playground safety chips should be delivered by the end of the week. needs more wood chips</i>	

Date: <i>3/13/24</i>	
Facility: <i>Croton</i>	
Location: <i>RV playground</i>	
IV. EQUIPMENT: SPECIFIC SWINGS	
S-hooks closed	<input checked="" type="checkbox"/>
Good chains/seats/hangers	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Equipment stable	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Check chain wear	<input checked="" type="checkbox"/>
Pads under swings present	<input checked="" type="checkbox"/>
SLIDES	
No loose steps or rails	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
No loose screws/bolts	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Exit pads in place	<input checked="" type="checkbox"/>
PLAY STRUCTURES	
Smooth surfaces	<input checked="" type="checkbox"/>
No metal rusts/wood rot	<input checked="" type="checkbox"/>
Stable/secure	<input checked="" type="checkbox"/>
No head entrapment	<input checked="" type="checkbox"/>
No loose handholds/rails	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
No missing parts	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
Adequate lubrication	<input checked="" type="checkbox"/>
No worn/frayed cables	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
CLIMBING APPARATUS	
No cut ropes	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
Secure anchor/footing	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
Adequate handhold size	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>



WESTCHESTER COUNTY

WESTCHESTER COUNTY

DEPARTMENT OF PARKS, RECREATION & CONSERVATION

Weekly Playground Inspection Report

I. GROUND HAZARD	
No holes/depressions	<input checked="" type="checkbox"/>
No unsecured fences/gates	<input checked="" type="checkbox"/>
No exposed footings	<input checked="" type="checkbox"/>
No broken glass/litter	<input checked="" type="checkbox"/>
No poor drainage areas	<input checked="" type="checkbox"/>

II. SURFACING

Type: Rubber

Depth:

Areas Need Surfacing/Raking:

III. EQUIPMENT: GENERAL

Smooth surfaces	<input checked="" type="checkbox"/>
Hardware in good condition	<input checked="" type="checkbox"/>
No entrapment/no angle	<input checked="" type="checkbox"/>
Capped ends	<input checked="" type="checkbox"/>
No sharp points, corners, edges, or loose welds	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
No projections	<input checked="" type="checkbox"/>
No pinch, crush, or shearing points	<input checked="" type="checkbox"/>
No tripping hazards	<input checked="" type="checkbox"/>
No suspended hazards (cables wires, ropes)	<input checked="" type="checkbox"/>
No equipment > 7 ft. high	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Litter can in good repair	<input checked="" type="checkbox"/>
Benches in good repair	<input checked="" type="checkbox"/>
Basketball nets OK	<input type="checkbox"/> <u>N/A</u>
Park sign ok	<input type="checkbox"/>
Over hanging limbs	<input checked="" type="checkbox"/>
Signs of vandalism	<input type="checkbox"/>
Park plantings OK	<input checked="" type="checkbox"/>

INSPECTOR

Name: RICK LANZA

Comments:

Date: 3-22-24

Facility: George's Island

Location: Upper PAV 1

IV. EQUIPMENT: SPECIFIC SWINGS

S-hooks closed	<input checked="" type="checkbox"/>
Good chains/seats/hangers	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Equipment stable	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Check chain wear	<input checked="" type="checkbox"/>
Pads under swings present	<input checked="" type="checkbox"/>

SLIDES

No loose steps or rails	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
No loose screws/bolts	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Exit pads in place	<input checked="" type="checkbox"/>

PLAY STRUCTURES

Smooth surfaces	<input checked="" type="checkbox"/>
No metal rusts/wood rot	<input checked="" type="checkbox"/>
Stable/secure	<input checked="" type="checkbox"/>
No head entrapment	<input checked="" type="checkbox"/>
No loose handholds/rails	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
No missing parts	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
Adequate lubrication	<input checked="" type="checkbox"/>
No worn/frayed cables	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>

CLIMBING APPARATUS

No cut ropes	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
Secure anchor/footing	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
Adequate handhold size	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>



WESTCHESTER COUNTY

WESTCHESTER COUNTY

DEPARTMENT OF PARKS, RECREATION & CONSERVATION

Weekly Playground Inspection Report

I. GROUND HAZARD	
No holes/depressions	<input checked="" type="checkbox"/>
No unsecured fences/gates	<input checked="" type="checkbox"/>
No exposed footings	<input checked="" type="checkbox"/>
No broken glass/litter	<input checked="" type="checkbox"/>
No poor drainage areas	<input checked="" type="checkbox"/>
II. SURFACING	
Type: WOOD CHIPS	
Depth: 12 INCHES	
Areas Need Surfacing/Raking:	
III. EQUIPMENT: GENERAL	
Smooth surfaces	<input checked="" type="checkbox"/>
Hardware in good condition	<input checked="" type="checkbox"/>
No entrapment/no angle	<input checked="" type="checkbox"/>
Capped ends	<input checked="" type="checkbox"/>
No sharp points, corners, edges, or loose welds	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
No projections	<input checked="" type="checkbox"/>
No pinch, crush, or shearing points	<input checked="" type="checkbox"/>
No tripping hazards	<input checked="" type="checkbox"/>
No suspended hazards (cables wires, ropes)	<input checked="" type="checkbox"/>
No equipment > 7 ft. high	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Litter can in good repair	<input checked="" type="checkbox"/>
Benches in good repair	<input checked="" type="checkbox"/>
Basketball nets OK	N/A
Park sign ok	<input checked="" type="checkbox"/>
Over hanging limbs	<input checked="" type="checkbox"/>
Signs of vandalism	<input checked="" type="checkbox"/>
Park plantings OK	<input checked="" type="checkbox"/>
INSPECTOR	
Name: <u>Shelton Lindsay</u>	
Comments: <u>old compacted chips removed - new chips added</u>	

Date: 3/28/24

Facility: Croton Point

Location: Gorge Playground

IV. EQUIPMENT: SPECIFIC SWINGS	
S-hooks closed	N/A
Good chains/seats/hangers	N/A
No broken parts	N/A
Equipment stable	N/A
Adequate surfacing	N/A
Check chain wear	N/A
Pads under swings present	N/A
SLIDES	
No loose steps or rails	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
No loose screws/bolts	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Exit pads in place	<input checked="" type="checkbox"/>
PLAY STRUCTURES	
Smooth surfaces	<input checked="" type="checkbox"/>
No metal rusts/wood rot	<input checked="" type="checkbox"/>
Stable/secure	<input checked="" type="checkbox"/>
No head entrapment	<input checked="" type="checkbox"/>
No loose handholds/rails	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
No missing parts	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
Adequate lubrication	<input checked="" type="checkbox"/>
No worn/frayed cables	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
CLIMBING APPARATUS	
No cut ropes	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
Secure anchor/footing	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
Adequate handhold size	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>



WESTCHESTER COUNTY

WESTCHESTER COUNTY

DEPARTMENT OF PARKS, RECREATION & CONSERVATION

Weekly Playground Inspection Report

I. GROUND HAZARD	
No holes/depressions	<input checked="" type="checkbox"/>
No unsecured fences/gates	<input checked="" type="checkbox"/>
No exposed footings	<input checked="" type="checkbox"/>
No broken glass/litter	<input checked="" type="checkbox"/>
No poor drainage areas	<input checked="" type="checkbox"/>
II. SURFACING	
Type: <i>Wood chips</i>	
Depth: <i>6"</i>	
Areas Need Surfacing/Raking: <i>UNDER SWINGS</i>	
III. EQUIPMENT: GENERAL	
Smooth surfaces	<input checked="" type="checkbox"/>
Hardware in good condition	<input checked="" type="checkbox"/>
No entrapment/no angle	<input checked="" type="checkbox"/>
Capped ends	<input checked="" type="checkbox"/>
No sharp points, corners, edges, or loose welds	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
No projections	<input checked="" type="checkbox"/>
No pinch, crush, or shearing points	<input checked="" type="checkbox"/>
No tripping hazards	<input checked="" type="checkbox"/>
No suspended hazards (cables wires, ropes)	<input checked="" type="checkbox"/>
No equipment > 7 ft. high	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Litter can in good repair	<input checked="" type="checkbox"/>
Benches in good repair	<input checked="" type="checkbox"/>
Basketball nets OK	<input type="checkbox"/> <i>N/A</i>
Park sign ok	<input checked="" type="checkbox"/>
Over hanging limbs	<input type="checkbox"/>
Signs of vandalism	<input checked="" type="checkbox"/>
Park plantings OK	<input checked="" type="checkbox"/>
INSPECTOR	
Name: <i>Rick LANZA</i>	
Comments:	

Date: *3-15-24*

Facility: *Blue MTN*

Location: *Center of PARK*

IV. EQUIPMENT: SPECIFIC SWINGS	
S-hooks closed	<input checked="" type="checkbox"/>
Good chains/seats/hangers	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Equipment stable	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Check chain wear	<input checked="" type="checkbox"/>
Pads under swings present	<input checked="" type="checkbox"/>
SLIDES	
No loose steps or rails	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
No loose screws/bolts	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Exit pads in place	<input type="checkbox"/>
PLAY STRUCTURES	
Smooth surfaces	<input checked="" type="checkbox"/>
No metal rusts/wood rot	<input checked="" type="checkbox"/>
Stable/secure	<input checked="" type="checkbox"/>
No head entrapment	<input checked="" type="checkbox"/>
No loose handholds/rails	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
No missing parts	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
Adequate lubrication	<input checked="" type="checkbox"/>
No worn/frayed cables	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
CLIMBING APPARATUS	
No cut ropes	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
Secure anchor/footing	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
Adequate handhold size	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>

Date: 4/1/24
 Facility: Willson's Woods Park
 Location: Lower Lot Childrens Playground

No Swing Wobble Board

I. GROUND HAZARD	
No holes/depressions	<input checked="" type="checkbox"/>
No unsecured fences/gates	<input checked="" type="checkbox"/>
No exposed footings	<input checked="" type="checkbox"/>
No broken glass/litter	<input checked="" type="checkbox"/>
No poor drainage areas	<input checked="" type="checkbox"/>

II. SURFACING	
Type: Poured Rubber	
Depth:	
Areas Need Surfacing/Raking:	

III. EQUIPMENT: GENERAL	
Smooth surfaces	<input checked="" type="checkbox"/>
Hardware in good condition	<input checked="" type="checkbox"/>
No entrapment/no angle	<input checked="" type="checkbox"/>
Capped ends	<input checked="" type="checkbox"/>
No sharp points, corners, edges, or loose welds	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
No projections	<input checked="" type="checkbox"/>
No pinch, crush, or shearing points	<input checked="" type="checkbox"/>
No tripping hazards	<input checked="" type="checkbox"/>
No suspended hazards (cables wires, ropes)	<input checked="" type="checkbox"/>
No equipment > 7 ft. high	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Litter can in good repair	<input checked="" type="checkbox"/>
Benches in good repair	<input checked="" type="checkbox"/>
Basketball nets OK	<input checked="" type="checkbox"/>
Park sign ok	<input checked="" type="checkbox"/>
Over hanging limbs	<input checked="" type="checkbox"/>
Signs of vandalism	<input checked="" type="checkbox"/>
Park plantings OK	<input checked="" type="checkbox"/>

INSPECTOR

Name: Wilson Thomas jr

Comments: Our playground doesn't have a swing but a Wobble Board.
 Everything is in good working order.

IV. EQUIPMENT	
SWINGS	
S-hooks closed	<input checked="" type="checkbox"/>
Good chains/seats/hangers	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Equipment stable	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Check chain wear	<input checked="" type="checkbox"/>
Pads under swings present	<input checked="" type="checkbox"/>
SLIDES	
No loose steps or rails	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
No loose screws/bolts	<input checked="" type="checkbox"/>
No broken parts	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
Exit pads in place	<input checked="" type="checkbox"/>
PLAY STRUCTURES	
Smooth surfaces	<input checked="" type="checkbox"/>
No metal rusts/wood rot	<input checked="" type="checkbox"/>
Stable/secure	<input checked="" type="checkbox"/>
No head entrapment	<input checked="" type="checkbox"/>
No loose handholds/rails	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
No missing parts	<input checked="" type="checkbox"/>
No protrusions	<input checked="" type="checkbox"/>
Adequate lubrication	<input checked="" type="checkbox"/>
No worn/frayed cables	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>
CLIMBING APPARATUS	
No cut ropes	<input checked="" type="checkbox"/>
No loose nuts/bolts	<input checked="" type="checkbox"/>
Secure anchor/footing	<input checked="" type="checkbox"/>
Smooth surfaces	<input checked="" type="checkbox"/>
Adequate handhold size	<input checked="" type="checkbox"/>
Adequate surfacing	<input checked="" type="checkbox"/>